

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg
GST: 201119451E RCB NO: 201119451E

M/S : Lonpac Insurance BHD
300 Beach Road #17-04/07
The Concourse
Singapore 199555
TEL: FAX:
ATTN: Motor Claim Department
Your Ref No: 22/LP/OD-273 (06)
Claim Type: OD Claim
Accident Date: 03/06/2022

Claim No :
No :
Date : 04/06/2022
Policy No : Z22VP05031004
Veh Reg No : SLB5499J
Make / Model : Honda Vezel
Chassis No : RUI-1106025
Engine No :
Reg. No :

Veron
\$ 11,109.35

ESTIMATE FOR VEHICLE NO: SLB5499J

Discription	Quantity	List Price	Amount
Cost Price			SS
1 FRT BONNET Distorted	1 PC	\$480.00	✓
2 FRT BONNET HINGE Bent	2PCS	\$90.00	✓
3 FRT BONNET LOCK Bent	1 PC	\$95.00	✓
4 FRT BONNET INSULATOR Crumpled	1 PC	\$115.00	✓
5 INSULATOR CLIP	10PCS	\$20.00	✓
6 FRT BONNET SIDE SEAL (WITH CLIP) None	2PCS	\$70.00	X
7 FRT BONNET LOCK CABLE Bent	1 PC	\$45.00	✓
8 FRT GRILLE Smashed	1 PC	\$270.00	✓
9 GRILLE OUTER GARNISH Smashed	1 PC	\$180.00	✓
10 GRILLE OUTER CHROME	2PCS	\$60.00	✓
11 GRILLE LOGO	1 PC	\$28.00	✓
12 GRILLE CLIP	6PCS	\$12.00	✓
13 GRILLE CTR BRACKET Crumpled	1 PC	\$35.00	✓
14 GRILLE SIDE BRACKET	2PCS	\$50.00	✓
15 FRT BUMPER Distorted	1 PC	\$250.00	✓
16 FRT BUMPER RETAINER None	2PCS	\$50.00	✓
17 FRT BUMPER CLIP	10PCS	\$20.00	✓
18 FRT BUMPER REINFORCEMENT Distorted	1 PC	\$280.00	✓
19 FRT BUMPER LOWER GRILLE Crumpled	1 PC	\$70.00	X
20 FRT BUMPER LOWER SPOILER Crumpled	1 PC	\$135.00	X
21 HEADLAMP Crumpled	2PCS	\$1,960.00	✓
22 HEADLAMP LOWER BRACKET Crumpled	2PCS	\$70.00	✓
23 HEADLAMP SUPPORT PANEL Distorted	1 PC	\$390.00	✓
24 SUPPORT TOP GARNISH	1 PC	\$50.00	✓
25 TOP GARNISH CLIP	8PCS	\$18.00	✓
26 AIRCON CONDENSER Distorted	1 PC	\$380.00	✓
27 RADIATOR Distorted	1 PC	\$850.00	✓
28 AIRCON FAN COWLING (INDENT) Crumpled	1 PC	\$145.00	X
29 AIRCON FAN MOTOR	1 PC	\$220.00	X
30 AIRCON FAN BLADE	1 PC	\$45.00	X
31 RADIATOR FAN COWLING Crumpled	1 PC	\$105.00	X
32 RADIATOR FAN MOTOR	1 PC	\$220.00	X
33 RADIATOR FAN BLADE	1 PC	\$55.00	X
34 RADIATOR TOP HOSE Crumpled	1 PC	\$25.00	✓
35 AIRCON SIDE DEFLECTOR Distorted	2PCS	\$70.00	✓
36 AIR DUCT Distorted	1 PC	\$65.00	✓
37 AIR HOSE Distorted	1 PC	\$50.00	✓
38 AIR CLEANER BOX TOP Crumpled	1 PC	\$75.00	✓
39 AIR CLEANER BOX LWR	1 PC	\$130.00	✓
40 BATTERY BRACKET	1 PC	\$25.00	✓
41 BATTERY TRAY Distorted	1 PC	\$30.00	✓
42 BATTERY POSITIVE COVER Distorted	1 PC	\$30.00	✓
43 MANIFOLD Crumpled	1 PC	\$320.00	✓
44 MANIFOLD HOSE Torn	1 PC	\$25.00	✓
45 AIRCON COOLING PIPE	1 PC	\$135.00	X
46 AIRCON DISCHARGE PIPE	1 PC	\$150.00	X
47 RADIATOR SPARE TANK	1 PC	\$40.00	X
48 WASHER TANK Distorted	1 PC	\$75.00	✓
49 WASHER TANK NECK Distorted	1 PC	\$35.00	✓
50 FRT WIPER CORNER GARNISH	2PCS	\$50.00	✓
51 FRT FENDER Crumpled	2PCS	\$380.00	✓
52 FRT FENDER PROTECTOR	2PCS	\$110.00	✓
53 WIPER GARNISH	1 PC	\$190.00	✓
54 THROTTLE BODY	1 PC	\$650.00	✓
		\$9,731.00	
		\$973.10	\$10,704.10

Add 15%

Manifold hose clip \$5 ✓

Manifold "Earthdram" emblem \$45 ✓
Nec

2pc Air Condenser bracket \$16 x 2 Bent ✓

2pc headlamp top bracket \$18 x 2 Crumpled ✓

Front bonnet stand. \$45 (missing) missing ✓

Ambience Sensor bracket \$15 (missing) missing ✓

Revised
Admin Lj Shg

7/29/

pecial Net
 FRT NUMBER PLATE *Best*
 RADIATOR COOLANT *for*
 FRT BONNET SEALANT *re*

1 PC
 1 PC
 1 PC

\$40.00
 \$25.00
 \$60.00
 \$125.00 ✓

Labour

- 1 WIRE CHECKING
- 2 REMOVE & REFIX AIRCON AND GAS
- 3 REMOVE & REFIX MANIFOLD & THROTTLE BODY
- 4 RESET SETTINGS
- 5 LABOUR CHARGE
- 6 SPRAY PAINTING

\$40.00 *30*
 \$100.00 *✓*
 \$250.00 *✓*
 \$200.00 *100*
 \$1,000.00 *500*
 \$1,200.00 *1000*
 \$2,790.00

2280
 14,310.35

Adnan Lij
Not Authorised

Excess: TBA

P/P 08Days

Amount Before Excess	\$13,619.10
Less Excess	\$0.00
Amount Before GST	\$13,619.10
Add GST @7%	\$1,361.91
Total Amount Payable	\$14,981.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: