

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL 6747 6106 (6 lines) Fax 6744 2368 Email service@smemotor.com.sg
GST 201119451E RCB NO 201119451E

M/S : Lonpac Insurance BHD
300 Beach Road #17-04/07
The Concourse
Singapore 199555

TEL : FAX :
ATTN: Motor Claim Department
Your Ref No : 22/LP/OD-273 (06)
Claim Type : OD Claim
Accident Date : 03/06/2022

Claim No :
No :
Date : 04/06/2022
Policy No : Z22VP05031004
Veh Reg No : SLB5499J
Make / Model : Honda Vezel
Chassis No : RUJ-1106025
Engine No :
Reg No :

ESTIMATE FOR VEHICLE NO: SLB5499J

Discription	Quantity	List Price	Amount
Cost Price			\$S
1 FRT BONNET <i>Distorted</i>	1 PC	\$480.00	✓
2 FRT BONNET HINGE <i>Best</i>	2PCS	\$90.00	✓
3 FRT BONNET LOCK <i>Distorted</i>	1 PC	\$95.00	✓
4 FRT BONNET INSULATOR <i>crushed</i>	1 PC	\$115.00	✓
5 INSULATOR CLIP <i>ne</i>	10PCS	\$20.00	✓
6 FRT BONNET SIDE SEAL (WITH CLIP) <i>ne ne</i>	2PCS	\$70.00	✓
7 FRT BONNET LOCK CABLE <i>3and</i>	1 PC	\$45.00	✓
8 FRT GRILLE <i>smashed</i>	1 PC	\$270.00	✓
9 GRILLE OUTER GARNISH <i>smashed</i>	1 PC	\$180.00	✓
10 GRILLE OUTER CHROME	2PCS	\$60.00	✓
11 GRILLE LOGO <i>ne</i>	1 PC	\$28.00	✓
12 GRILLE CLIP <i>ne</i>	6PCS	\$12.00	✓
13 GRILLE CTR BRACKET <i>crushed</i>	1 PC	\$35.00	✓
14 GRILLE SIDE BRACKET	2PCS	\$50.00	✓
15 FRT BUMPER <i>Distorted</i>	1 PC	\$250.00	✓
16 FRT BUMPER RETAINER <i>ne</i>	2PCS	\$50.00	✓
17 FRT BUMPER CLIP <i>ne</i>	10PCS	\$20.00	✓
18 FRT BUMPER REINFORCEMENT <i>Distorted</i>	1 PC	\$280.00	✓
19 FRT BUMPER LOWER GRILLE <i>3 ne ne</i>	1 PC	\$70.00	✓
20 FRT BUMPER LOWER SPOILER	1 PC	\$135.00	✓
21 HEADLAMP <i>crushed</i>	2PCS	\$1,960.00	✓
22 HEADLAMP LOWER BRACKET <i>crushed</i>	2PCS	\$70.00	✓
23 HEADLAMP SUPPORT PANEL <i>Distorted</i>	1 PC	\$390.00	✓
24 SUPPORT TOP GARNISH <i>Distorted</i>	1 PC	\$50.00	✓
25 TOP GARNISH CLIP <i>ne</i>	8PCS	\$16.00	✓
26 AIRCON CONDENSER <i>Distorted</i>	1 PC	\$380.00	✓
27 RADIATOR <i>Distorted</i>	1 PC	\$850.00	✓
28 AIRCON FAN COWLING (INDENT) ?	1 PC	\$145.00	✓
29 AIRCON FAN MOTOR ?	1 PC	\$220.00	✓
30 AIRCON FAN BLADE ?	1 PC	\$45.00	✓
31 RADIATOR FAN COWLING ?	1 PC	\$105.00	✓
32 RADIATOR FAN MOTOR ?	1 PC	\$220.00	✓
33 RADIATOR FAN BLADE ?	1 PC	\$55.00	✓
34 RADIATOR TOP HOSE <i>twisted</i>	1 PC	\$25.00	✓
35 AIRCON SIDE DEFLECTOR <i>Distorted</i>	2PCS	\$70.00	✓
36 AIR DUCT <i>Distorted</i>	1 PC	\$65.00	✓
37 AIR HOSE <i>Distorted</i>	1 PC	\$50.00	✓
38 AIR CLEANER BOX TOP <i>3 ne ne</i>	1 PC	\$75.00	✓
39 AIR CLEANER BOX LWR <i>ne ne</i>	1 PC	\$130.00	✓
40 BATTERY BRACKET ?	1 PC	\$25.00	✓
41 BATTERY TRAY ?	1 PC	\$30.00	✓
42 BATTERY 'POSITIVE' COVER <i>Distorted</i>	1 PC	\$30.00	✓
43 MANIFOLD ?	1 PC	\$320.00	✓
44 MANIFOLD HOSE <i>ne ne</i>	1 PC	\$25.00	✓
45 AIRCON COOLING PIPE ?	1 PC	\$135.00	✓
46 AIRCON DISCHARGE PIPE ?	1 PC	\$150.00	✓
47 RADIATOR SPARE TANK ?	1 PC	\$40.00	✓
48 WASHER TANK <i>Distorted</i>	1 PC	\$75.00	✓
49 WASHER TANK NECK <i>Distorted</i>	1 PC	\$35.00	✓
50 FRT WIPER CORNER GARNISH <i>ne ne</i>	2PCS	\$60.00	✓
51 FRT FENDER <i>Distorted</i>	2PCS	\$380.00	✓
52 FRT FENDER PROTECTOR <i>ne ne</i>	2PCS	\$110.00	✓
53 WIPER GARNISH <i>3 ne ne</i>	1 PC	\$190.00	✓
54 THROTTLE BODY	1 PC	\$850.00	✓
		\$9,731.00	
		\$973.10	
		\$10,704.10	

Add 10%

Special Net		
1	FRT NUMBER PLATE <i>Best</i>	1 PC \$40.00
2	RADIATOR COOLANT <i>per</i>	1 PC \$25.00
3	FRT BONNET SEALANT <i>pc</i>	1 PC \$60.00
		\$125.00

Labour		
1	WIRE CHECKING	\$40.00 <i>30</i>
2	REMOVE & REFIX AIRCON AND GAS	\$100.00 <i>✓</i>
3	REMOVE & REFIX MANIFOLD & THROTTLE BODY	\$250.00 <i>?</i>
4	RESET SETTINGS	\$200.00 <i>100</i>
5	LABOUR CHARGE	\$1,000.00 <i>800</i>
6	SPRAY PAINTING	\$1,200.00 <i>1000</i>
		\$2,790.00

Amount Before Excess	\$13,619.10
Less Excess	\$0.00
Amount Before GST	\$13,619.10
Add GST @7%	\$1,361.91
Total Amount Payable	\$14,981.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
Not Authorised

Excess: TBA.

P/P 08Days.