

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melody Teoh

Date: 06 Jul 2022

Preliminary Advice

Vehicle No	: SLB363A	Accident Date	: 01/06/2022
Make	: BMW X1	Policy No.	: SMPG21012586
Assignment Date	: 06/06/2022	Excess	: S\$500.00
Date of Inspection	: 20/06/2022	Est. Duration of Repair	: 8
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 22,416.00	(Estimate \$17,498.25 + Supplementary \$4,917.75)
Revised Amount	:S\$ 9,766.20	
Check Items (Estimated)	:S\$ 9,533.80	
Total	:S\$ 19,300.00	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 101,000.00
COE / PARF Rebate	:S\$ 45,456.00
Salvage Value	:S\$
Margin for Repair	:S\$ 55,544.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.