

# Performance Motors Limited



## FACSIMILE MESSAGE

DATE 6 Jul 2022 TIME                     

INS Ergo FAX NO                     

NO OF PAGES                     

SUV Steve Chen

ATTN LKK FAX NO                     

MCA Foong S J FAX NO 64743229

TEL NO                     

If the fax is not received in order, please do call CSA. Thank you

Dear Sirs,

Supplementary repair for BM\X1

Vehicle Registration No. SLB363A

Vehicle Chassis No. 5F02296

**Supplementary Parts to replace** YES ☒ Refer to attachment

NO ☐

Part / Labour Description *	QTY	Prices
Reference to supplementary part quotation #624489	1	\$1,297.70
Additional labour to replace front bumper top carrier, impact absorber top and air duct.	1	\$850.00
Reference to supplementary part quotation #624488	1	\$1,032.05
To replace radiator assembly and check for leak	1	\$785.00
To replace air con condenser and check for leak	1	\$953.00
<b>Request for additional 3 work days</b> ✓		
<b>Total =&gt;</b>		<b>\$4,917.75</b>

425 ✓

✓

✓

\* All of the above which are highlighted will be considered as agreeable if there is no objection and/OR subsequence amendment within 3 work days.