

SERVICE ESTIMATE

NR898 - 00001
 Mr Wong Wei Chen
 556 Yishun Avenue 6
 #11-11

SEE SERVICE SALES - PG

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 06/06/2022

WIP No. : 27877

Veh. In/Out:

*Tel.No. : Mobile: 92203780

Reg.No. : SLN754S

Reg.date : 21/04/2017

Mileage : 0

Chassis No: YV1MV28H0H2426934

Sinecode 768964

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Wong Wei Chen

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE LHF FENDER, FRONT BUMPER, BRACKETS, CLIPS, ETC	850 x 1.5	2550.00	0		2,550.00 S	1275 ✓
803	TO BLEND AND SPRAY PAINT ON LHF FENDER, FRONT BUMPER, ETC.	750 x 2	2250.00	0		2,250.00 S	1500 ✓
0031	TO REPLACE LHF RIM	0	50.00	0		50.00 S	✓
10	WHEEL ALIGNMENT	0	280.00	0		280.00 S	✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	588.00	0		588.00 S	✓
	BUMPER COVER FRT V40	1 X NN 1.0 EA	1865.70	DEF		1,865.70 S	✓ 1679.13
	BUMPER BRACKET FRT L	1 X NN 1.0 EA	107.90			107.90 S	
	BUMPER BRACKET LHF V	1 X NN 1.0 EA	182.10			182.10 S	
	BUMPER REINFORCEMENT	1 X NN 1.0 EA	182.10			182.10 S	
	FENDER PANEL FRT LH	1 X NN 1.0 EA	1262.80			1,262.80 S	✓ 1136.52
	WHEELARCH FRT LH V40	1 X NN 1.0 EA	253.00			253.00 S	
	ALLOY RIM 16 "Markeb	1 X NN 1.0 EA	749.10			749.10 S	✓ 674.19
	BUMPER CLIP GREEN S6	1 X NN 10.0 EA	6.00			60.00 S	

- This estimate is valid only for the vehicle described above.
- The price is based on the current market rate.
- The price is subject to change without prior notice.
- The price is subject to change without prior notice.
- The price is subject to change without prior notice.
- The price is subject to change without prior notice.

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

88898 - C00001
 Mr Wong Wei Chen
 556 Yishun Avenue 6
 #11-13

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 06/06/2022

WIP No. : 27877

Veh.In/Out:

*Tel.No. : Mobile: 92203780

Reg.No. : SLN754S

Reg.date : 21/04/2017

Mileage : 0

Chassis No: YV1MV28HOH2426934

Singapore 768964

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Wong Wei Chen

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER CLIP XC90 16-	1X NN 10.0 EA	8.80			88.00	S
	BUMPER CLIP 8x8,5	1X NN 10.0 EA	8.20			82.00	S
	BLIND RIVET 4.0*21 P	1X NN 10.0 EA	5.00			50.00	S
	BUMPER INSTALLING MT	1X NN 1.0 EA	101.40			101.40	S

Steve (LKK)
 25/7/22, 9.45am

m R
 P/P
 L BL L
 5 L

		Gross Total.	10,702.10
Labour Total	5,718.00	Net.....	10,702.10
Parts Total	4,984.10	GST @ 7.0%	749.15
Package Total	0.00	Total.....	11,451.25
		Paid.....	0.00
		Please Pay..	11,451.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 36 ROBINSON ROAD Inv.No. . : B&P 0 Page 1
 #16-01, CITY HOUSE Inv.date. : 19/08/2022
 SINGAPORE WIP No. . : 27877
 Singapore 068877 Veh.In/Out: 25/07/2022 08/08/2022
 *Tel.No. . :
 Reg.No. . : SLN754S
 Closed by : Michelle Ong Siew Be Reg.date . : 21/04/2017
 Svc Consultant : ACC Mileage .. : 73,476
 Remarks : Mr Wong Wei Chen Chassis No: YV1MV28H0H2426934

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE LHF FENDER, FRONT BUMPER, BRACKETS, CLIPS, ETC	0	1275.00	0		1,275.00	S ✓
800	TO BLEND AND SPRAY PAINT ON LHF FENDER, FRONT BUMPER, ETC.	0	1500.00	0		1,500.00	S ✓
0031	TO REPLACE LHF RIM	0	50.00	0		50.00	S ✓
10	WHEEL ALIGNMENT	0	280.00	0		280.00	S ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	588.00	0		588.00	S ✓
	⑤ FENDER PANEL FRT LH	1.0 EA	1262.80	10		1,136.52	S
	② ALLOY RIM 16 "Markeb	1.0 EA	749.10	10		674.19	S
	① BUMPER COVER FRT V40	1.0 EA	1865.70	10		1,679.13	S

Gross Total. 7,182.84

Labour Total 3,693.00
 Parts Total 3,489.84
 Package Total 0.00

Net..... 7,182.84
 GST @ 7.0% 502.80
 Total..... 7,685.64
 Paid..... 0.00
 Please Pay.. 7,685.64

GST: S=StdRated; O=OutOfScope; Z=ZeroRated