

J.E.W MOTORS PTE LTD

Address: 60 Jalan Lam Huat, #03-72
CARROS CENTER, Singapore 737869

Repair Quotation

Vehicle number: SMJ9468T
Model and make: Hyundai Accent
Chassis number: KMHCU41BT KU464841

Insurance company:

No.	Spare parts	Qty	Amount
1	Front bumper	1	\$ 445.00 <i>de ✓</i>
2	Front bumper clips	1set	\$ 80.00 <i>30 ✓</i>
3	Front bumper LH fog lamp	1	\$ 313.00 <i>cut ✓</i>
4	Front bumper LH fog lamp wire harness	1	\$ 367.00 <i>x nn ✓</i>
5	Front bumper RH side retainer	1	\$ 27.00 <i>x nn ✓</i>
6	Front bumper LH side retainer	1	\$ 27.00 <i>cut ✓</i>
7	Front bumper LH upper bracket	1	\$ 22.00 <i>x nn ✓</i>
8	Front bumper inner sponge	1	\$ 132.00 <i>cut ✓</i>
9	LH headlamp assy	1	\$ 821.00 <i>cut ✓</i>
10	Support panel	1	\$ 792.00 <i>x nn ✓</i>
11	Front grille	1	\$ 235.80 ✓ 387.00 <i>cut ✓</i>
12	Front grille emblem	1	\$ 45.00 <i>cut ✓</i>
13	Front grille clips	1set	\$ 20 ✓ 30.00 <i>20 ✓</i>
14	Front LH fender	1	\$ 483 ✓ 598.00 <i>bt ✓</i>
15	Front LH fender splash shield	1	\$ 72.00 <i>bt ✓</i>
16	Front LH fender splash shield clips	1set	\$ 10 ✓ 60.00 <i>10 ✓</i>
17	Front LH shock absorber	1	\$ 404.00 <i>x ✓</i>
18	Front LH shock absorber top mounting	1	\$ 78.00 <i>x ✓</i>
19	Front LH lower arm	1	\$ 463.00 <i>x ✓</i>
20	Front LH knuckle arm	1	\$ 505.00 <i>x ✓</i>
21	Front LH wheel bearing	1	\$ 488.00 <i>x ✓</i>
22	Front LH tie rod end	1	\$ 97.00 <i>x ✓</i>
23	Front LH drive shaft	1	\$ 983.00 <i>x ✓</i>
24	Steering rack and pinion	1	\$ 1,308.00 <i>x ✓</i>
2633.80			\$ 8,544.00
-20%			\$ 1,708.80
2107.04			Total \$ 6,835.20

No.	Spare parts	Qty	Special Nett
1	Front LH tyre	1	\$ 450.00 <i>x nn ✓</i>
2	Front LH sport rim	1	\$ 1,200.00 <i>cut ✓</i>
			500

3	Brake fluid	1	\$	80.00	X un
4	Radiator coolant	1	\$	90.00	X un

500

LABOUR

1	Labour charges to provide workmanship cut / weld and replacing of parts		\$	1,300.00	500
2	Spray paint on affected and consistent areas		\$	1,200.00	500
3	Check wiring and lighting system		\$	100.00	30
4	Apply rust chemical on affected areas		\$	80.00	30
5	Refocus and adjust headlamps assy		\$	100.00	30
6	Remove and refit radiator assy and hoses to carry repair		\$	280.00	X un
7	Remove and refit aircon condenser and pipe to carry repair		\$	280.00	X un
8	Adjust and test drive wheel alignment system	provide alignment report	\$	100.00	80? X un
9	Remove and replace front undercarriage parts		\$	450.00	120? X un photo

1090

Total: \$ 12,545.20

3697.04 + 308 (supp) = 4005.04

L/S - 3204.03
= 3200

Taufik 97495749
WR / 9/6/27 @ 130pm
To check consistency of accident
& part price.
L/S Resurvey after repair
taufik@lkkauto.com
05 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: