

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT969H Yr Regn: 22/9/17Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Subaru Levorg c.c. 1600Colour: Gray A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 80044 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: JFTRM4K 5536006067Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 215/45R18R: 11BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or . _____

Front: _____ Rear: _____

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 3/5/22 D.O.I. 8/6/22Survey held at Motor ImageDes. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop orRan LH

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

MV-85K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.F. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0095/2022
DATE : 03-JUN-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : LIM TONG HUAY (LIN DONGHUI)
ADDRESS : APT BLK 119 TECK WHYE LANE
#09-794
S(680119)
TELEPHONE NO : 9796 4421

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700055832-04
VEHICLE NO : SLT969H
MODEL CODE : VM4DK15
MODEL/YEAR : LEVORG 1.6GT-S AWD CVT
ENGINE NO : FB16CA71640
CHASSIS NO : JF1VM4K55JG006067
MILEAGE : 1 KM
DATE IN : 03/06/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 31/05/2022

Print Date : 03/06/2022
Print Time : 14:34:52

IMAGE ENTERPRISES PTE. LTD.
LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT969H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST GBB2872C - CN TAIPING INSURED		
2 ZZ/001	CONDUCT TP CLAIM CN TAIPING DATE:31/05/2022 TIME: 0907HRS LOCATION:JLN JURONG KECHIL TO UPP BKT TIMH		
3 ZZ/002	REPAIR/REPLACE LH REAR DOOR, LH REAR FENDER, LH REAR ROCKER PANEL & PANEL <i>560</i>	2240.00	✓
4 ZZ/003	RESPRAY REAR LH DOOR, REAR LH FENDER, REAR LH ROCKER PANEL & PANEL <i>470</i>	1680.00	<i>1260</i>
5 ZZ/004	TRANSFER DOOR REAR LH MECHANISM	200.00	<i>150</i>
6 ZZ/005	REMOVE & INSTALL LH REAR QUARTER GLASS	180.00	✓
7 ZZ/006	CONDUCT REAR PROTECTANT COATING <i>(sahm agreed)</i>	500.00	?
8 ZZ/007	SUPPLY & INSTALL LH REAR QUARTER GLASS TINTED FILM	145.00	✓
9 ZZ/008	SUNDRIES <i>(sahm agreed)</i>	100.00	<i>77</i>
TOTAL LABOUR CHARGES		5045.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLT969H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 VALVE TPMS ASSY	28103FJ003	185.00	/	NEC	
2 PNL SD OUT QTR RPLH	51439VA0319P	888.00	/	DD	
3 QTR PNL R END CPLLH	51445VA0309P	22.20	/	NEC	
4 PNL COMPL DR R WLH	60409VA0509P	666.00	/	DD	
5 LATCH&ACT AY DR RLH	61035VA210	185.00	X		
6 HANDLE OUT DR	61160FJ000EN	48.10	X		
7 WSTR OUT DR R LH	62280VA131	96.20	X		
8 WSTR DR R LH	63512VA110	129.50	X		
9 GLASSRUN DR R WLH	63527VA130	62.90	X		
10 WSTR BODY SD FLG R	63572VA021	85.10	X		
11 WDW GL ASSY R QTRLH	65210VA171	599.40	X	NEC	
12 DAM RUBBER A	65245VA000	7.40	/	NEC	
13 DAM RUBBER B	65245VA010	7.40	/	NEC	
14 TAPE DR SASH R F LH	90422VA570	18.50	/	NEC	
15 TAPE DR SASH R M LH	90422VA590	14.80	/	NEC	
16 TAPE DR SASH R R LH	90422VA610	14.80	/	NEC	
SUB TOTAL		3030.30	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		606.06	0.00	0.00	0.00
GRAND TOTAL		2424.24	0.00	0.00	0.00
OVERALL TOTAL		2424.24			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLT969H

TOTAL LABOUR CHARGES	5045.00
TOTAL SPARE PARTS CHARGES	2424.24
GRAND TOTAL	7469.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

Stere (LKK)
8/6/22, 10.00am

WZ M
P/P
M BL Sy
6 yr

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: