

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0095/2022
DATE : 03-JUN-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : LIM TONG HUAY (LIN DONGHUAI)
ADDRESS : APT BLK 119 TECK WHYE LANE
#09-794
S(680119)
TELEPHONE NO : 9796 4421

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700055832-04
VEHICLE NO : SLT969H
MODEL CODE : VM4DK15
MODEL/YEAR : LEVORG 1.6GT-S AWD CVT
ENGINE NO : FB16CA71640
CHASSIS NO : JF1VM4K55JG006067
MILEAGE : 1 KM
DATE IN : 03/06/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 31/05/2022

Print Date : 03/06/2022
Print Time : 14:34:52

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT969H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST GBB2872C - CN TAIPING INSURED		
2	ZZ/001	CONDUCT TP CLAIM CN TAIPING DATE:31/05/2022 TIME: 0907HRS LOCATION:JLN JURONG KECHIL TO UPP BKT TIMH		
3	ZZ/002	REPAIR/REPLACE LH REAR DOOR, LH REAR FENDER,LH REAR ROCKER PANEL & PANEL	2240.00	
4	ZZ/003	RESPRAY REAR LH DOOR, REAR LH FENDER, REAR LH ROCKER PANEL & PANEL	1680.00	
5	ZZ/004	TRANSFER DOOR REAR LH MECHANISM	200.00	
6	ZZ/005	REMOVE & INSTALL LH REAR QUARTER GLASS	180.00	
7	ZZ/006	CONDUCT REAR PROTECTANT COATING	500.00	
8	ZZ/007	SUPPLY & INSTALL LH REAR QUARTER GLASS TINTED FILM	145.00	
9	ZZ/008	SUNDRIES	100.00	
		TOTAL LABOUR CHARGES	5045.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLT969H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	VALVE TPMS ASSY	28103FJ003	185.00			
2	PNL SD OUT QTR RPLH	51439VA0319P	888.00			
3	QTR PNL R END CPL LH	51445VA0309P	22.20			
4	PNL COMPL DR R WLH	60409VA0509P	666.00			
5	LATCH&ACT AY DR RLH	61035VA210	185.00			
6	HANDLE OUT DR	61160FJ000EN	48.10			
7	WSTR OUT DR R LH	62280VA131	96.20			
8	WSTR DR R LH	63512VA110	129.50			
9	GLASSRUN DR R WLH	63527VA130	62.90			
10	WSTR BODY SD FLG R	63572VA021	85.10			
11	WDW GL ASSY R QTRLH	65210VA171	599.40			
12	DAM RUBBER A	65245VA000	7.40			
13	DAM RUBBER B	65245VA010	7.40			
14	TAPE DR SASH R F LH	90422VA570	18.50			
15	TAPE DR SASH R M LH	90422VA590	14.80			
16	TAPE DR SASH R R LH	90422VA610	14.80			
SUB TOTAL			3030.30	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			606.06	0.00	0.00	0.00
GRAND TOTAL			2424.24	0.00	0.00	0.00
OVERALL TOTAL			2424.24			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLT969H

TOTAL LABOUR CHARGES	5045.00
TOTAL SPARE PARTS CHARGES	2424.24
GRAND TOTAL	7469.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.