



FALCON-AIR

B 2 B SERVICES
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
ATTN: MR ALBERT TAN - 96334293
Attention: Motor Claim Department

FALCON-AIR AUTO SERVICES PTE LTD
Co. Reg No.: 199501140D
GST Reg. No.: 199501140D

*Not Notified
Running Repair*

5 days

84058.22

Estimate : ES012405

Date : 06/06/2022
Vehicle Num. : GBK 4109M
Make/Model : NISSAN NV200 (PETROL)-2020
Chassis/Eng#: JN1YAAM20Z0001082
Accident Date : 28/05/2022
Claim No. : SNM22D203831
Reference : TP - NTUC AGT CHINA TAIPING
Policy No. : 5122696490

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1. 1 PC
2. 1 PC
3. 1 PC
4. 1 PC
5. 1 PC
6. 1 PC
7. 1 PC
8. 1 PC

NETT ITEMS : *1635*
TAILGATE
TAILGATE LOGO
TAILGATE EMBLEM - NV200
REAR END PANEL (OUTER)
REAR END PANEL TOP GARNISH
TAILGATE WEATHERSTRIP
REAR BUMPER
REAR BUMPER SPONGE

Pr 1,635.00 ✓
na 64.90 ✓
na 94.40 ✓
na 193.50 ✓
na 87.90 ✓
na 106.40 ✓
na 485.90 ✓
CM 94.00 ✓

Nett Total S\$:
10.00% Discount S\$:

2,762.00
276.20
2,485.80

1. 1 PC
2. 1 PC
3. 6 PCS
4. 1 PC
5. 12 PCS
6. 1 SET
7. 1 PC

SPECIAL NETT ITEMS :
6 PAX STICKER
70 km/h STICKER
REAR END PANEL TOP GARNISH CLIP
TAILGATE GLASS SEALANT
REAR BUMPER CLIP
REVERSE SENSOR
TAILGATE BODY SEALANT

na 25.00 *121n*
na 25.00 *121n*
na 60.00 ✓
na 45.00 *405n*
na 36.00 ✓
na 250.00 *200n*
na 80.00 *305n*

Special Nett Total S\$:

521.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Head Office :
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Website: www.falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

B 2 B SERVICES
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
ATTN: MR ALBERT TAN - 96334293
Attention: Motor Claim Department

Estimate : ES012405

Date : 06/06/2022
Vehicle Num. : GBK 4109M
Make/Model : NISSAN NV200 (PETROL)-2020
Chassis/Eng# : JN1YAAM20Z0001082
Accident Date : 28/05/2022
Claim No. : SNM22D203831
Reference : TP - NTUC AGT CHINA TAIPING
Policy No. : 5122696490

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :				
		TO REMOVE/REFIX TAILGATE GLASS	120.00	✓
		TO REMOVE/REFIX TAILGATE MECHANISM	100.00	601
		TO REFIT REVERSE SENSOR IN NEW BUMPER	50.00	✓
		TO RUSTPROOF ACCIDENT DAMAGE AREA	150.00	601
		TO CUT OUT/RE-WELD REAR END PANEL OUTER, REPAIR REAR		
		END PANEL INNER, REAR CHASSIS INCLUDING REPLACEMENT OF		
		PARTS	700.00	6501
		TO SPRAY PAINT ON TAILGATE, REAR END PANEL OUTER/INNER	750.00	5001
Labour Total S\$:				1,870.00

E. & O.E.

Total S\$: 4,876.80

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Head Office :
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Website: www.falconair.com.sg