

ASS. REC. BY:

REF:

C12 / 22005372/k

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1.81

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBK 4109M Yr Regn: 07, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS

NV200

C.G

1598

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

52511

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1YAA M20Z 0001082

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

28/5/22

D.O.I.

7/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

F. Ins

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$



FALCON-AIR

B 2 B SERVICES
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
ATTN: MR ALBERT TAN - 96334293
Attention: Motor Claim Department

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

Not Authorized
Recovery Bk paint

5 days

Estimate : ES012405

Date : 06/06/2022
Vehicle Num. : GBK 4109M
Make/Model : NISSAN NV200 (PETROL)-2020
Chassis/Eng#: JN1YAAM20Z0001082
Accident Date : 28/05/2022
Claim No. : SNM22D203831
Reference : TP - NTUC AGT CHINA TAIPING
Policy No. : 5122696490

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|------|----------------------------|--|--|
| 1. | 1 PC | NETT ITEMS : | | |
| 2. | 1 PC | TAILGATE | | |
| 3. | 1 PC | TAILGATE LOGO | | |
| 4. | 1 PC | TAILGATE EMBLEM - NV200 | | |
| 5. | 1 PC | REAR END PANEL (OUTER) | | |
| 6. | 1 PC | REAR END PANEL TOP GARNISH | | |
| 7. | 1 PC | TAILGATE WEATHERSTRIP | | |
| 8. | 1 PC | REAR BUMPER | | |
| | | REAR BUMPER SPONGE | | |

Nett Total S\$:

10.00% Discount S\$:

2,762.00

276.20

2,485.80

- | | | | | |
|----|--------|---------------------------------|--|--|
| 1. | 1 PC | SPECIAL NETT ITEMS : | | |
| 2. | 1 PC | 6 PAX STICKER | | |
| 3. | 6 PCS | 70 km/h STICKER | | |
| 4. | 1 PC | REAR END PANEL TOP GARNISH CLIP | | |
| 5. | 12 PCS | TAILGATE GLASS SEALANT | | |
| 6. | 1 SET | REAR BUMPER CLIP | | |
| 7. | 1 PC | REVERSE SENSOR | | |
| | | TAILGATE BODY SEALANT | | |

Special Nett Total S\$:

521.00

CONTINUE / ...

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 23 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

B 2 B SERVICES

C/O 176 SIN MING DRIVE #01-06/07

SIN MING AUTOCARE 575721

ATTN: MR ALBERT TAN - 96334293

Attention : Motor Claim Department

Estimate : ES012405

Date : 06/06/2022

Vehicle Num. : GBK 4109M

Make/Model : NISSAN NV200 (PETROL)-2020

Chassis/Eng# : JN1YAAM20Z0001082

Accident Date : 28/05/2022

Claim No. : SNM22D203831

Reference : TP - NTUC AGT CHINA TAIPING

Policy No. : 5122696490

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO REMOVE/REFIX TAILGATE GLASS

120.00

TO REMOVE/REFIX TAILGATE MECHANISM

100.00

TO REFIT REVERSE SENSOR IN NEW BUMPER

50.00

TO RUSTPROOF ACCIDENT DAMAGE AREA

150.00

TO CUT OUT/RE-WELD REAR END PANEL OUTER, REPAIR REAR
END PANEL INNER, REAR CHASSIS INCLUDING REPLACEMENT OF
PARTS

700.00

TO SPRAY PAINT ON TAILGATE, REAR END PANEL OUTER/INNER

750.00

Labour Total S\$:

1,870.00

E. & O.E.

Total S\$:

4,876.80

=====

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/06/2022 11:25 (SGT)
Date of Accident	28/05/2022 20:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG JALAN BESAR
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBK4109M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	B 2 B SERVICES
Company Reg No	5XXXXX95C
Email Address	dnumd3y0@outlook.com
Mobile Phone No	(Phone) +65-96334293
Alternative Phone No	+65-96251144

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	NV200 1.6 (A) PETROL
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5122696490
Cover Note Number	-

DRIVER



Name of Driver	CHEN YIHONG, EDMOND
NRIC No	SXXXX479Z

...ability on the part of the insurance Association of ...
...by the General Insurance Association ...
...application by interested parties ...
...Centre and to copies of the ...


Jalan Besar Plaza



Royal Indian Res.



Kithener Road



Hotel Nuve

