ENROUTE PERFORMANTE PTE LTD

QUOTATION FOR REPAIR: FBF3108Z

		Repairer's
Qty	Description	Estimate
	R/ MIRORR	\$75.00 40 ✓ BR
	CLUTCH LEVER	\$89.00 30 ✓ CUT
	BRAKE LEVER	\$89.00 30 ✓ CUT
	SIDE STAND	\$148.00 × NN
	L/R FRONT FOOT REST	\$134.00 120 ✓ BT
	R/ REAR FOOT REST	\$134.00 × NN
	EXHAUST COVER LONG/SHORT	\$348.00 150 ✓ CUT
	HEADLIGHT COWLING (Headlamp)	\$146.00 CUT
	BIKE PLATE (Handle grip)	\$15.00 V TN
	L/R HANDLER BAR	\$155.00 ✓ BT
	L/R TAIL COVER (front body cover)	\$189.00 ✓ CUT
	FRONT FENDER	\$126.00 105 ✓ CUT
	BASKET (Rear carrier bracket)	\$78.00 ✓ BT

Total Part :	1,553.40
Less 10%	1,726.00

Nett items

Total Nett items:	0.00	
Total parts:	1,553.40	
Labour Fee		
BODY FRAME RE-ALIGNMENT	800.00	150
FORK RE-ALIGNMENT	380.00	200
FRONT RIM RE-ALIGNMENT	380.00	150
LABOUR TO DISMANTLE AND ASSEMBLE PARTS	1,200.00	300
Total Labour Fee:	2,760.00	
Total parts and labour charges:	4,313.40	

PRI BY:

DISMANTLE BY:

4 days

7 DAYS

AFTER REPAIR BY:

COST PRICE FOR REPAIR:

3RD PTY INSURANCE -