

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005379/UPA3Q2**Date:** 12/09/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJX5259T**Insured Vehicle No :** GBF9509K

Date of Loss: 03/06/2022

Nature of Claim: TP

Claim No: 4511227789SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJX5259T**

Make & Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)

Engine No: 07347433N52B25AF

Reg. Date: 23/06/2010 (Man. Year: 2010)

Chassis No: WBAFP32080C544486

Colour: Grey

Odometer: 141235 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,465.75	2,517.40	5,948.35	70.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	2,030.00	1,060.00	34.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,555.75	4,547.40	7,008.35	60.65
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	11,555.75	3,600.00	7,955.75	68.85
+ GST 7.00/7.00% (S\$)	808.90	252.00	556.90	68.85
Nett Amount (S\$)	12,364.65	3,852.00	8,512.65	68.85
+ Car Rental (4.0 x S\$150.00/day + 7.00% GST) (S\$)		642.00		
(S\$)		4,494.00		
Liabile Amount (50.00%) (S\$)		2,247.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,249.00		
Global Sum Settlement (S\$)		2,240.00		

INSPECTION

Date of Assignment: 07/06/2022

Date Inspected: 07/06/2022 Inspected At:

Stytech Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub

Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR N/S	Repair	1,810.35 F	*- FL
2	1		*REAR DOOR N/S	Bent / Warped	1,766.90 F	*1,766.90 FL
3	1		*REAR DOOR INNER RUBBER N/S	Necessary	262.00 F	*262.00 FL
4	1		*SIDE SKIRT N/S	Cut / Torn	621.00 F	*621.00 FL
5	1		*ROCKER PANEL N/S	Repair	725.00 F	*- FL
6	1		*REAR FENDER N/S	Repair	1,880.20 F	*- FL
7	1		*REAR FENDER UNDERSHIELD N/S	Not Necessary	250.30 F	*- FL
8	1		*REAR SPORT RIM N/S	Repair	1,100.00 F	*- FL
9	1		*REAR FENDER GLASS SEALANT	Not Necessary	50.00 F	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					8,465.75	2,649.90
- List Item Discount on L Items 0.00/5.00% (S\$)					0.00	132.50
Total Parts (S\$)					8,465.75	2,517.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
2	TO TRANSFER FRONT DOOR MECHANISM	New	120.00	0.00
3	TO TRANSFER REAR DOOR MECHANISM	New	120.00	80.00
4	TO CHECK WIRING	New	100.00	20.00
5	TO SPRAY ANTI RUST PROOFING	New	100.00	30.00
6	LABOUR CHARGE	New	1,000.00	800.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
Gross Labour Cost (\$\$)			3,090.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >