

STX52597

Date

No.

1PC	Front door nls	R	1810.35	X
1PC	Rear door nls	Rebuilt/rep	1766.90	/
1PC	Rear door inner rubber nls	nec	262.00	/
1PC	side skirt nls	cut/torn	621.00	/
1PC	Rocker panel nls	R	725.00	X
1PC	Rear fender nls	R	1880.20	X
1PC	Rear fender under-shield nls	11	250.30	X
1PC	Rear sport rim nls	R	1100.00	X
1PC	Rear fender glass sealant	11	50.00	X
		(S2)	8465.75	

To Dismantle & Refix rear windscreen	11	150.00	X
To transfer front door mechanism	11	120.00	X
To transfer Rear door mechanism		120.00	80
To check w.ring		100.00	20
To spray ant. rust proofing		100.00	30
labour charge		1000.00	800
To putty & spray painting		1500.00	1100
		TOTAL @	11555.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed

AM

7/6/27

1/5 @ 3600

Hans

P-2648.9

S2

2517.40

2030

4847.4

203

3637