

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192
SINGAPORE 510607
BUSINESS REGN. No. 53193457L
Email: willybit@gmail.com / Mobile: 96699986

VEHICLE DAMAGE INSPECTION REPORT

98 Car Rental
c/o Goh JP & Wong LLC
133 New Bridge Road # 16-09
Chinatown Point
Singapore 059413

Our Ref : PA/FBF6891/1121/tpw
Date : 02 December 2021

REFERENCES

Claim Type	: Third Party	Date of Accident	: 23 October 2021
Vehicle No	: FBF 6891 A	Date of Assignment	: 12 November 2021
Make	: Yamaha	Date of Inspection	: 12 November 2021
Model	: T135	Date of Re-inspection	: 22 & 24 November 2021
Registration Date	: 15 October 2011	COE Expiry	: 14 October 2031
Color	: Black	Chassis No	: 5YP303486
Odometer	: 20,159 km	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Pirelli	70/90-17	5mm
Rear	Pirelli	80/90-17	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and left sides.
Please refer to photographs and assessment of repairs for details
Enclosed (66) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$4,365.78 Revised Assessment \$3,050.00 Lump sum

Survey conducted at Hua Chin (2000) Trading Motor Service Centre

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Five (5) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBF 6891 A

Our Ref: PA/BBF6891/1121/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

<u>S/N</u>	<u>Description Material</u>	<u>Qty</u>	<u>Condition</u>	<u>Original Quotation</u>	<u>Revised Quotation</u>	
1	Handle bar upper cover - front	1 pc	Hdr cracked	98.50	98.50	× NN
2	Handle bar upper cover - Rear	1 pc	Hdr cracked	83.60	83.60	× NN
3	Handle bar	1 pc	Bent	105.00	105.00	✓
4	Handle bar bracket	1 pc	Distorted	65.00	65.00	✓
5	Handle grip	1 set	Serviceable	60.00	~	× NN
6	Balancer	1 set	Cut	50.00	50.00	✓
7	Clutch lever	1 pc	Cut	35.30	35.30	× NN
8	Mirror	1 set	Grazed	110.00	110.00	60 ✓
9	Front cowling	1 pc	Hdr cracked	145.00	145.00	× NN
10	Head lamp assy	1 pc	Scratch	130.00	130.00	× NN
11	Front side shield @ \$103/- (RH) 1	2 pcs	Hdr cracked	206.00	206.00	103 ✓
12	Middle frame cover	1 pc	Hdr cracked	150.00	150.00	× NN
13	Crankcase cover LH	1 pc	Cracked	165.80	165.80	✓
14	Front fork assy @ \$420/-	2 pcs	Bent	840.00	840.00	× NN
15	Under bracket	1 pc	Distorted	160.00	160.00	× NN
16	Front rim	1 pc	Warped	320.00	320.00	× NN
17	Front disc plate	1 pc	Serviceable	135.00	~	
18	Front footrest bar	1 pc	Bent	90.00	90.00	✓
19	Gear pedal	1 pc	Bent	65.00	65.00	× NN
20	Tail cover LH (RH)	1 pc	Cut	120.00	120.00	✓
				3,134.20	2,939.20	
List price less 10%				313.42	293.92	
				2,820.78	2,645.28	
<u>Add special net item</u>						
21	Steering cone / bearing	1 set	Necessary	120.00	60.00	✓
22	Crankcase gasket	1 pc	Necessary	25.00	25.00	✓
23	Engine oil	3 lits	Necessary	60.00	30.00	✓
24	Central basket	1 pc	Deformed	50.00	40.00	× NN
25	Sticker	1 set	Necessary	160.00	120.00	✓
				415.00	275.00	

PRUDENT ADJUSTORS SERVICES

Vehicle No: **FBF 6891 A**

Our Ref: PA/FBF6891/1121/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Labour charge

Front mudguard repair (Paint)	80.00	60.00	✓
Body frame repair	550.00	450.00	200
Renew & repair accident parts	500.00	400.00	200
	<u>1,130.00</u>	<u>910.00</u>	

Total parts & labour concluded	<u>4,365.78</u>	<u>3,830.28</u>
--------------------------------	-----------------	-----------------

Final lump sum repair adjustment	3 days	<u>3,050.00</u>
----------------------------------	---------------	------------------------

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



Prudent Adjustors Services
Bok Jee Tan