

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 05.07.2022
 VEH NO : SMH483T
 MODEL : Honda Shuttle
 D O A : 31.05.2022
 YR REF : SLG7788K

Celia

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMH483T (HONDA SHUTTLE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Door - RH <i>Dented</i>	1	1,050.40 ✓
2	Front Door Weatherstripe - RH <i>new</i>	1	168.40 +
3	Front Door Glass Regulator Gear - RH <i>new</i>	1	244.90 +
4	Front Door Inner Trimboard - RH <i>new</i>	1	625.40 +
5	Rear Door - RH <i>Dented</i>	1	1,078.40 ✓
6	Rear Door Weatherstripe - RH <i>new</i>	1	172.50 +
7	Rear Door Glass Regulator - RH <i>Dented</i>	1	256.90 ✓
8	Rear Door Inner Trimboard - RH <i>new</i>	1	615.10 +
9	Rocker Panel - RH <i>Dented</i>	1	695.80 ✓
10	Rocker Panel Outer Garnish - RH <i>new</i>	1	589.40 ✓
			5,497.20
Less 20%			(1,099.44)
			\$ 4,397.76

S/NETT ITEMS

1	Front Door Inner Trimboard Clips - RH <i>new</i>	1 set	\$ 30.00 +
2	Front Door Black Tape - RH <i>new</i>	1	\$ 60.00 ✓
3	Front Door Visor - RH	1	\$ 100.00 80.
4	Rear Door Inner Trimboard Clips - RH <i>new</i>	1 set	\$ 30.00 +
5	Rear Door Black Tape - RH <i>new</i>	1	\$ 60.00 ✓
6	Rear Door Visor - RH	1	\$ 100.00 80.
7	Rocker Panel Outer Garnish Clips <i>new</i>	1 set	\$ 30.00 ✓
			\$ 410.00
Total Parts			\$ 4,807.76

RE : ESTIMATE FOR ACCIDENT REPAIR SMH483T (HONDA SHUTTLE)

LABOUR CHARGE

1	To knocking & pull out front & rear door portion & renew above parts	\$	1,100.00 700
2	To putty & spray up paint works	\$	1,100.00 800
3	To check wiring	\$	50.00 30
4	To spray tuff coat	\$	150.00 60
5	To transfer front door fittings	\$	150.00 80
6	To transfer rear door fittings	\$	150.00 80
7	To remove upholstery	\$	200.00 60
Total Labour		\$	2,900.00
Grand Total		\$	7,707.76

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 5056.72
L/S: 4050.
06 Days.