

ASS. REC. BY: T. AuphREF: 05/TM/2200530/1111 Tny3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Amey Vehicle: IN / OUTVeh No: SUA5383L Yr Regn: 2020, MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i10 C.C. 1580Colour: blue A/C: Insured / Std / NI / NASp. Reading: 36649 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVLY 189571Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 1 -BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Wipac

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at Comfort byngDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 21/6/22

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/08/22 confirmed final fig: \$1019.60 and 2 days
(red, \$2048.04/ 67%)

Date/Time, File Pass to?

1) 15/08/22

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.B. (\$ 1019.60)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/06/2022
Vehicle Reg. No.:	SHA5383L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	11/03/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU407489	Chassis No:	KMHC851CVLU189571
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,886.64
Miscellaneous Items	11.00
Labour	1,170.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	3,067.64
+ GST 7.00% (\$)	214.73
Nett Amount (\$)	3,282.37

This claim is handled by: **CHIANG LIAT CHOON**

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2022)

Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FL <i>Ry</i>
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*451.25 FL <i>de</i>
3	1		*REAR BUMPER REINFORCEMENT BEAM	20.00	0.00	*394.80 FL <i>?</i>
4	2		*REAR BUMPER REINFORCEMENT BEAM TOP BRACKET L/R	20.00	0.00	*276.20 FL <i>?</i>
5	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>ne</i>
6	2		*REAR BUMPER SIDE RETAINER -L/R	20.00	0.00	*111.60 FL <i>X</i>
7	1		*REAR BUMPER FOG LAMP	20.00	0.00	*201.50 FL <i>X</i>
8	1		*REAR NUMBER PLATE LIGHT LAMP	20.00	0.00	*85.30 FL <i>X</i>
9	1		*REAR NUMBER PLATE W/HOLDER	0	0.00	*55.00 FS <i>X</i>
10	1		*REAR REVERSE SENSOR	0	0.00	*180.00 FS <i>?</i>
11	1		*REAR BUMPER MAT	0	0.00	*50.00 FS <i>X</i>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,287.05
- List Item Discount on L Items (S\$)	400.41
Total Parts (S\$)	1,886.64

ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	350	750.00
2	SPRAY PAINTING	New	250	300.00
3	CHECK LIGHTING % WIRING	New	A	60.00
4	REMOVE/REFIX REVERSE SENSOR	New	30	60.00

Gross Labour Cost (S\$)

1,170.00

ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphi 97495749
wp 7/6/22 @ 345
p/p Resurvey new parts
2 days
Tanphi MC Whitman

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 07.06.2022 09:42

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4254112

JC NO.305518748

CUSTOMER

MR/MS **COMFORT TRANSPORTATION PTE LTD**
CUSTOMER NO. **7010045**
ADDRESS **383 SIN MING DRIVE**
Singapore SINGAPORE 575717
TEL. (R) **65508755** (O)

DISCOUNT CARD NO.

REGN NO:
SHA5383L

MAKE:
HYUNDAI

MODEL
IONIQ(G3)

YR OF MANU.
11.03.2020

CHASSIS CODE
KMHC851CVLU189571

MILEAGE

FUEL

E.....1/2.....

DATE/TIME IN
06.06.2022 15:15

TARGET DATE

COMPLETION DATE/TIME


JOB DESCRIPTION

Accident Date: 06.06.2022
NATURE: 3P 06.06.2022

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

ame:

o No.:

ehicle No.:

SHA5383L

CHIANG

Exit Pass

Vehicle No.:

SHA5383L

ame of Service Advisor

Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard