

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 09 Jun 2022

Preliminary Advice

Insured	: GBE1214T		
Vehicle No			
TP Vehicle	: SNB5505B	Accident Date	: 26/05/2022
No			
Make	: TESLA MODEL 3	Assignment Date	: 07/06/2022
	PERFORMANCE		
Date of	: 08/06/2022	Est. Duration of	: 2
Inspection		Repair	
Inspection At	: OPTIMA WERKZ PTE LTD (HQ)		
	10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05 AMK		
	AUTOPOINT		
	SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,497.20
Revised Amount	:S\$	1,142.20
Check Items (Estimated)	:S\$	120.00
Total	:S\$	1,262.20

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.