

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22005392/UVY3N2**Date:** 17/06/2022**REFERENCE**

Insured/Claimant:	LOW BOON KENG	Policy No:	D22MPC0002769	
Date of Loss:	05/06/2022	Nature of Claim:	OD	Claim No: MPC2022D0002959

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2960Z		
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Engine No:	G4FGHU620782
Reg. Date:	19/09/2017 (Man. Year: 2017)	Chassis No:	KMHD841CMJU542010
Colour:	Red	Odometer:	110150 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,389.60	4,182.40	207.20	4.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,325.00	1,910.00	1,415.00	42.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,714.60	6,092.40	1,622.20	21.03
Approved Total (Overridden) (S\$)		4,800.00		
- Excess (S\$)	850.00	850.00	0.00	0.00
Nett Amount (S\$)	6,864.60	3,950.00	2,914.60	42.46

INSPECTION

Date of Assignment:	07/06/2022		
Date Inspected:	09/06/2022	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

FOR MANDATE ONLY

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS2960Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S SIDE MIRROR	Cut/Damaged	638.00 FL	*638.00 FL
2	1		*FRONT N/S DOOR	Bent	1,904.00 FL	*1,904.00 FL
3	1		*SET FRONT N/S DOOR FRAM STICKER	Necessary	56.00 FL	*56.00 FL
4	15		*FRONT N/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	90.00 FL	*- FL
5	1		*REAR N/S DOOR	Dented/Bent	1,878.00 FL	*1,878.00 FL
6	1		*SET REAR N/S DOOR FRAME STICKER	Necessary	46.00 FL	*46.00 FL
7	16		*REAR N/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	96.00 FL	*- FL
8	8		*REAR N/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FL	*- FL
9	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
10	1		*REAR BUMPER N/S SIDE RETAINER	Not Necessary	45.00 FL	*- FL
11	1		*REAR N/S SPORT RIM	Cut	671.00 FL	*671.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,487.00	5,228.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,097.40	1,045.60
Total Parts (\$)	4,389.60	4,182.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	45.00	20.00
2	TO REMOVE & REFIX FRONT & REAR N/S DOOR INNER TRIM BOARD COVER,GLASS,MOULDING,WEATHERSTRIP,HANDLE,GARNISH & NECESSARY PARTS,TO ENABLE REPAIR NECESSARY PARTS	New	240.00	100.00
3	TO REMOVE & REFIX CUSHION SEAT,REAR N/S FENDER INNER SHIELD,CARPET,FLOOR MAT,GARNISH & NECESSARY PARTS,TO ENABLE REPAIR REAR N/S FENDER & NECESSARY PARTS	New	120.00	80.00
4	TO CHECK & ADJUST WHEEL ALIGNMENT & BALANCING	New	120.00	60.00
5	TO RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,500.00	1,100.00
6	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	1,300.00	550.00
Gross Labour Cost (\$\$)			3,325.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >