

Plate Number	Case Number	Brand	Model Details	Body Type	Insurance company	Export CSV
SLS2960Z	MPC2022D0002959	Hyundai	Elantra	Sedan	India International Insurance	
Technician -	SA LKK_assignments	Parts Manager -				

## Parts

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	FRONT N/S MIRROR <div>Customized</div>			\$0.00	\$638.00	-20 %	1	\$510.40
02	FRONT N/S DOOR <div>Customized</div>			\$0.00	\$1904.00	-20 %	1	\$1523.20
03	FRONT N/S DOOR FRAME STICKER <div>Customized</div>			\$0.00	\$56.00	-20 %	1	\$44.80
04	REAR N/S DOOR <div>Customized</div>			\$0.00	\$1878.00	-20 %	1	\$1502.40
05	REAR N/S DOOR FRAME STICKER <div>Customized</div>			\$0.00	\$46.00	-20 %	1	\$36.80
06	REAR BUMPER CLIPS <div>Customized</div>			\$0.00	\$35.00	-20 %	1	\$28.00
07	REAR N/S SPORT RIM <div>Customized</div>			\$0.00	\$671.00	-20 %	1	\$536.80
Total :								\$4182.40

## Labors

Replace / RnR

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
---	-------------	------------	------	------------	------------	--------------	-----

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
01	CHECK WIRE <div>Customized</div>		RnR	0.00	\$20.00	0 %	\$20.00
02	REMOVE AN D REFIX FRO NT AND REA R DOOR INNE R TRIM <div>Customized</div>		RnR	0.00	\$100.00	0 %	\$100.00
03	REMOVE AN D REFIX INTE RIOR ATTACH MENT <div>Customized</div>		RnR	0.00	\$80.00	0 %	\$80.00
04	WHEEL ALIG NMENT <div>Customized</div>		RnR	0.00	\$60.00	0 %	\$60.00
05	PANEL BEAT AND REPLAC EMENT DAMA GE ITEMS <div>Customized</div>		RnR	0.00	\$550.00	0 %	\$550.00
							Total :\$810.00

Paint

#	Description	Labor Code	degree	Labor Hour	Unit Price	Mark up/Disc	Sum
01	PAINT AFPEC TED AREA <div>Customized</div>		Full spray	0.00	\$1100.00	0 %	\$1100.00
							Total :\$1100.00

Remarks 2 remarks

2022-06-15 11:48 Assessor Supervisor-Insurlogic 1 6584981566

Final review: Concluded the cost of repair at lump sum \$4800.00 with 5 days for repair

2022-06-13 15:15 Assessor Supervisor-Insurlogic 1 6584981566

Pre Review done base on survey information provided

Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic

Amount : \$6092.40

Lump sum: \$4800.00

Repair Duration: 5 days

---