

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gabriel Wee

Date: 09 Jun 2022

Preliminary Advice

Vehicle No	: SLS2960Z	Accident Date	: 05/06/2022
Make	: HYUNDAI ELANTRA	Policy No.	: D22MPC0002769
Assignment Date	: 07/06/2022	Excess	: S\$0.00
Date of Inspection	: 9/6/2022	Est. Duration of Repair	: 5
Inspection At	: HUP MOTOR TRADING & SERVICE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,714.60
Revised Amount	:S\$	6,092.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,092.40
Lump Sum Repair	:S\$	4,800.00 (estimated)

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	28,505.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,495.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost