

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3068/06/22 Your Ref: Date: 15th JUNE 2022

The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
64, Cecil Street, #05-00, IOB Bldg.
Singapore 049711

Name Of Insured : Mr Low Boon Keng
Date Of Accident : 05/06/22 (23:45hrs)
Policy Number : D22MPC0002769

Cost of repair to HYUNDAI ELANTRA 1.6 (A) Saloon - SLS 2960 Z

To supply front n/s side mirror, front n/s door, frame sticker, rear n/s door, frame sticker, rear bumper clips, rear n/s sport rim & necessary parts.

To remove & refix front & rear n/s door inner trim board cover, glass, regulator, channel, lock, handle, weatherstrip, moulding & necessary parts.

To remove & refix rear cushion seat, carpet, floor mat, garnish, floor board cover, rear n/s fender inner shield & necessary parts.

To check & adjust wheel alignment & balancing, including wiring check up for affected wiring system.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s fender & necessary parts, to weld, renew & align above parts.

To putty & respray painting on all affected accident parts.

Lump Sum Repair :	\$ 4,800.00
Less Excess :	\$ 850.00
Balance :	\$ 3,950.00
	=====

Dollars : Three Thousand Nine Hundred And Fifty Only.

HUP MOTOR TRADING & SERVICE

Encl : Discharge Voucher