



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS/III22005392/y3	
			Date: 07/06/2022	
			Code: III2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLS 2960Z
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	BHUVANESWARI	Assign Date	07/06/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	05/06/2022	Inspection Date	09/06/2022
	Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			