



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 23rd June 2022

Our Ref: CC2/MIDA22005400/Epq2

M/s Ministry Of Defence

AFPN 0042

321 GOMBAK DRIVE

#02-05

SINGAPORE 669648

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMR 3604P
ACCIDENT DATE: 26/04/2021**

We refer to the above matter.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMR 3604P from M/s Wearnes Automotive Pte. Ltd.
- b) Singapore Accident Statement and Police Report of Vehicles SMR 3604P.
- c) Colour damaged vehicle photographs of SMR 3604P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMR 3604P
Make & Model	: Jaguar XE 2.0P 200PS RWD
Year of Registration	: 2019
Chassis Number	: SAJAB4AX4KCP50666
Engine Capacity	: 1997 cc

2. Our finding is that the repair cost of \$108,061.66 (before GST) quoted by M/s Wearnes Automotive Pte. Ltd. is fair & reasonable.

3. We recommend that the repairs of the entire damage require about 20 (Twenty) working days to complete.

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor



ADRIAN LING WAI PING
*B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.