



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

~~Supplementary~~ Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2205-295 TG
DATE : 6-Jun-2022
POLICY NO. : PNPV2020-00010497-01
VEHICLE REG. NO. : SLT5591E
VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Steve (LKK)
6/6/22, 11.00am
Lump-sum
Without Prejudice
Resurvey After Spray
7 days

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Door (RH) ✓ DD	1	\$ 1,832.00	\$ 1,832.00
2	Front Door Lock (RH) ?	1	\$ 192.00	\$ 192.00
3	Front Door Checker (RH) ✗	1	\$ 35.00	\$ 35.00
4	Front Door Handle (RH) ✓ CUT	1	\$ 18.00	\$ 18.00
5	Front Door Handle Cap (RH) ✓ CUT	1	\$ 25.00	\$ 25.00
6	Front Door Weatherstrip (RH) ?	1	\$ 130.00	\$ 130.00
7	Front Door Top Black Tape (RH) ✓ NEC	1	\$ 20.00	\$ 20.00
8	Front Door Side Black Tape (RH) ✓ NEC	1	\$ 20.00	\$ 20.00
9	Rear Door (RH) ✓ DD	1	\$ 1,775.00	\$ 1,775.00
10	Rear Door Lock (RH) ✗	1	\$ 192.00	\$ 192.00
11	Rear Door Checker (RH) ✗	1	\$ 35.00	\$ 35.00
12	Rear Door Hinge Top (RH) ✓ BT	1	\$ 35.00	\$ 35.00
13	Rear Door Hinge Bottom (RH) ✓ BT	1	\$ 30.00	\$ 30.00
14	Rear Door Weatherstrip (RH) ✗	1	\$ 105.00	\$ 105.00
15	Rear Door Top Black Tape (RH) ✓ NEC	1	\$ 20.00	\$ 20.00
16	Rear Door Side Black Tape (RH) ✓ NEC	1	\$ 20.00	\$ 20.00
17	B' Pillar (RH) ?	1	\$ 3,920.00	\$ 3,920.00
18	Rocker Panel (RH) ✓ DD	1	\$ 1,800.00	\$ 1,800.00
Parts Less 20%				\$ (2,040.80)
Total Spare Parts				\$ 8,163.20
LABOUR				
10	Repair, Remove, Refit and Replace Affected Accident Parts	1	\$ 1,300.00	\$ 1,300.00
11	Spray Painting (Front Door (RH), Rear Door (RH), Front Fender (RH), Rocker Panel (RH), 'B' Pillar (RH))	1	\$ 1,300.00	\$ 1,300.00
12	Apply Rust Proofing on Replaced/Repaired Panels	1	\$ 100.00	\$ 100.00
13	Transfer door fitting and window mechanism to new door	2	\$ 50 80.00	\$ 160.00
14	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 2,910.00
Amount Before Excess				\$ 11,073.20
Add GST @ 7%				775.12
Total Amount Payable				\$ 11,848.32

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

1000
1000
30
100
30