

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122005403/AQY3Q2**Date:** 01/02/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMQ9915H **Insured Vehicle No :** SLB363A

Date of Loss: 01/06/2022 Nature of Claim: TP Claim No: CDMPG22001039-002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ9915H**

Make & Model: TOYOTA NOAH, 1.8 (A) Engine No: 2ZR0E70294

Reg. Date: 13/12/2019 (Man. Year: 2019) Chassis No: ZWR800415199

Colour: Silver Odometer: 115210 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,152.72	9,504.27	6,648.45	41.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	2,700.00	1,350.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,202.72	12,204.27	7,998.45	39.59
+ GST 7.00/7.00% (S\$)	1,414.19	854.30	559.89	39.59
Nett Amount (S\$)	21,616.91	13,058.57	8,558.34	39.59

INSPECTION

Date of Assignment: 06/06/2022

Date Inspected: 06/06/2022 Inspected At: Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2023)
Parts:	M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ9915H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,894.60 FL	*1,894.60 FL
2	2		*BOOT LID HINGE	Not Necessary	199.20 FL	*- FL
3	2		*BOOT LID SHOCK ABSORBER	Not Necessary	494.20 FL	*- FL
4	1		*BOOT LID CHROME	Cut	712.70 FL	*712.70 FL
5	1		*BOOT LID LOGO	Necessary	101.60 FL	*101.60 FL
6	1		*BOOTLID HYBRID SYNERGY DRIVE EMBLEM	Necessary	91.90 FL	*91.90 FL
7	1		*BOOT LID SIDE BLACK GARNISH	O/S Cut	379.20 FL	*189.60 FL
8	2		*REAR NUMBER PLATE LAMP	Not Necessary	145.60 FL	*- FL
9	1		*REAR WINDSCREEN RUBBER WITH GLASS ASSY	Necessary	1,880.30 FL	*285.00 FL
10	1		*BOOT LID TRIM	Deformed	669.30 FL	*669.30 FL
11	1		*BOOT LID LOCK	Damaged	663.10 FL	*486.00 FL
12	1		*BOOT LID LOCK CHECKER	Bent	55.60 FL	*55.60 FL
13	2		*BOOT LID SIDE CHECKER	Not Necessary	191.20 FL	*- FL
14	1		*BOOT LID HOLDING GARNISH	Deformed	79.40 FL	*79.40 FL
15	1		*BOOT LID RUBBER	Cut	367.90 FL	*367.90 FL
16	1		*BOOT LID OPENER HANDLE	Not Necessary	299.10 FL	*- FL
17	2		*BOOTLID SIDE SMALL STOPPER	Not Necessary	58.20 FL	*- FL
18	1		*TAIL LAMP -RH	Cut	1,318.70 FL	*781.00 FL
19	1		*REAR BUMPER TOP BUMPER RH	Deformed	396.10 FL	*396.10 FL
20	1		*TAIL LAMP LH	Not Necessary	1,318.70 FL	*- FL
21	1		*REAR PANEL	Dented	735.70 FL	*735.70 FL
22	1		*REAR PANEL TRIM	Deformed	299.60 FL	*299.60 FL
23	1		*SPARE TYRE PANEL	Repair	825.20 FL	*- FL
24	1		*SPARE TYRE PANEL TRIM	Not Necessary	616.50 FL	*- FL
25	1		*SPARE TYRE TOP COVER	Deformed	928.90 FL	*791.00 FL
26	1		*SPARE TYRE TOOL COVER	Deformed	212.10 FL	*212.10 FL
27	1		*REAR FENDER INNER TRIM RH	Deformed	897.90 FL	*897.90 FL
28	1		*REAR FENDER INNER TRIM LH	Not Necessary	897.90 FL	*- FL
29	1		*REAR BUMPER	Deformed	1,080.10 FL	*1,080.10 FL
30	2		*REAR BUMPER SIDE RETAINER	Necessary	326.80 FL	*150.00 FL
31	1		*REAR BUMPER REFLECTOR -RH	Cracked	78.90 FL	*78.90 FL
32	1		*REAR ANTENNA SENSOR	Cracked	166.40 FL	*166.40 FL
33	2		*REAR BUMPER LONG RETAINER	Cracked	394.40 FL	*190.00 FL
34	1		*REAR BUMPER KEYLESS SENSOR	Cracked	207.50 FL	*207.50 FL
35	1		*BOOT LID BLACK LINING	Necessary	100.00 FS	*60.00 FS
36	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
37	1		*REVERSE CAMERA	Damaged	480.00 FS	*480.00 FS
38	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*30.00 FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
40	1		*SET BOOTLID TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
41	1		*SET REAR PANEL TIM CLIPS	Necessary	60.00 FS	*20.00 FS
42	1		*SET REAR FENDER RH INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
43	1		*SET REAR FENDER INNER TRIM LH CLIPS	Not Necessary	80.00 FS	*- FS
44	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
45	1		*SET REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
46	2		*REAR BUMPER STICKER	Necessary	400.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR JACK BRACKET	Bent	205.80 FL	*205.80 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					20,950.30	12,285.70
- List Item Discount on L Items 25.00/25.00% (\$\$)					4,797.58	2,781.43
Total Parts (\$\$)					16,152.72	9,504.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT THIRD BRAKE LIGHT	New	80.00	0.00
3	TO REMOVE AND REFIT BOOTLID (FITTINGS)	New	80.00	80.00
4	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
5	TO REMOVE AND REFIT VIDEO CAMERA	New	80.00	50.00
6	TO REMOVE AND REFIT REVERSE CAMERA	New	80.00	50.00
7	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
8	TO REMOVE AND REFIT INNER TRIM	New	180.00	60.00
9	TO SPRAY PAINT SEALANT	New	100.00	60.00
10	(REAR) TO SPRAY PAINTING	New	1,400.00	1,200.00
11	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,800.00	1,000.00
Gross Labour Cost (\$\$)			4,050.00	2,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >