

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 01/06/2022
TP Veh Reg No: SLB363A

Estimate No: EST2200171

Date: 02 Jun 2022

Veh Reg No: **SMQ9915H**
Make/Model: TOYOTA NOAH
HYBRID 1.8X CVT

Chasis No: ZWR800415199

Reg. Date: 13/12/2019

Your Ref No: SLB363A

Estimate Repair Cost to Vehicle No :SMQ9915H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	1,894.60	
2	2 PCS BOOT LID HINGE	199.20	
3	2 PCS BOOT LID SHOCK ABSORBER	494.20	
4	1 PC BOOT LID CHROME	712.70	
5	1 PC BOOT LID LOGO	101.60	
6	1 PC BOOTLID "HYBRID SYNERGY DRIVE" EMBLEM	91.90	
7	2 PCS BOOT LID SIDE BLACK GARNISH	379.20	
8	2 PCS REAR NUMBER PLATE LAMP	145.60	
9	1 PC REAR WINDSCREEN RUBBER WITH GLASS ASSY	1,880.30	
10	1 PC BOOT LID TRIM	669.30	
11	1 PC BOOT LID LOCK	663.10	
12	1 PC BOOT LID LOCK CHECKER	55.60	
13	2 PCS BOOT LID SIDE CHECKER	191.20	
14	1 PC BOOT LID HOLDING GARNISH	79.40	
15	1 PC BOOT LID RUBBER	367.90	
16	1 PC BOOT LID OPENER HANDLE	299.10	
17	2 PCS BOOTLID SIDE SMALL STOPPER	58.20	
18	1 PC TAIL LAMP - RH	1,318.70	
19	1 PC REAR BUMPER TOP BUMPER RH	396.10	
20	1 PC TAIL LAMP LH	1,318.70	
21	1 PC REAR PANEL	735.70	
22	1 PC REAR PANEL TRIM	299.60	
23	1 PC SPARE TYRE PANEL	825.20	
24	1 PC SPARE TYRE PANEL TRIM	616.50	
25	1 PC SPARE TYRE TOP COVER	928.90	
26	1 PC SPARE TYRE TOOL COVER	212.10	
27	1 PC REAR FENDER INNER TRIM RH	897.90	
28	1 PC REAR FENDER INNER TRIM LH	897.90	
29	1 PC REAR BUMPER	1,080.10	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 01/06/2022
TP Veh Reg No: SLB363A

Estimate No: EST2200171

Date: 02 Jun 2022

Veh Reg No: **SMQ9915H**
Make/Model: TOYOTA NOAH
HYBRID 1.8X CVT

Chasis No: ZWR800415199

Reg. Date: 13/12/2019

Your Ref No: SLB363A

Estimate Repair Cost to Vehicle No :SMQ9915H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	2 PCS REAR BUMPER SIDE RETAINER	326.80	
31	1 PC REAR BUMPER REFLECTOR - RH	78.90	
32	1 PC REAR ANTENNA SENSOR	166.40	
33	2 PCS REAR BUMPER LONG RETAINER	394.40	
34	1 PC REAR BUMPER KEYLESS SENSOR	207.50	
		18,984.50	
	Less 25%	4,746.13	14,238.47
	Special Net		
35	1 PC BOOT LID BLACK LINING	100.00	
36	1 PC REAR NUMBER PLATE	50.00	
37	1 PC REVERSE CAMERA	480.00	
38	1 PC REAR WINDSCREEN SEAL	60.00	
39	1 PC REAR WINDSCREEN SEALANT	60.00	
40	1 SET BOOTLID TRIM CLIPS	80.00	
41	1 SET REAR PANEL TIM CLIPS	60.00	
42	1 SET REAR FENDER RH INNER TRIM CLIPS	80.00	
43	1 SET REAR FENDER INNER TRIM LH CLIPS	80.00	
44	1 SET REAR BUMPER CLIPS	60.00	
45	1 SET REVERSE SENSORS	250.00	
46	2 PCS REAR BUMPER STICKER	400.00	
		1,760.00	1,760.00
	Labour		
47	1 TO CHECK WIRING	50.00	
48	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00	
49	1 TO REMOVE AND REFIT BOOTLID SPOILER	80.00	
50	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
51	1 TO REMOVE AND REFIT VIDEO CAMERA	80.00	
52	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
53	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 01/06/2022
TP Veh Reg No: SLB363A

Estimate No: EST2200171

Date: 02 Jun 2022

Veh Reg No: **SMQ9915H**

Make/Model: TOYOTA NOAH
HYBRID 1.8X CVT

Chasis No: ZWR800415199

Reg. Date: 13/12/2019

Your Ref No: SLB363A

Estimate Repair Cost to Vehicle No :SMQ9915H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
54	1 TO REMOVE AND REFIT INNER TRIM	180.00	
55	1 TO SPRAY PANEL SEALANT	100.00	
56	1 (REAR) TO SPRAY PAINTING	1,400.00	
57	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00	
		4,050.00	4,050.00
		Total	S\$ 20,048.47
		Add GST @ 7%	1,403.39
		Total Amount Payable	<u>S\$ 21,451.86</u>

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND FOUR HUNDRED FIFTY ONE AND CENTS EIGHTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE