

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199

FAX: 68299247

ATTN: Motor Claim Department

Estimate No: EST2200171

Date: 02 Jun 2022

Veh Reg No: SMQ9915H

Make/Model: TOYOTA NOAH
HYBRID 1.8X CVT

Chasis No: ZWR800415199

Reg. Date: 13/12/2019

Your Ref No: SLB363A

Claim Type: Third Party

Accident Date: 01/06/2022

TP Veh Reg No: SLB363A

Xiao Chun

Estimate Repair Cost to Vehicle No :SMQ9915H

Quantity	Description	List Price SS	Amount SS
1	1 PC BOOT LID <i>Dented</i>	1,894.60	✓
2	2 PCS BOOT LID HINGE <i>new</i>	199.20 +	
3	2 PCS BOOT LID SHOCK ABSORBER <i>new</i>	494.20 +	
4	1 PC BOOT LID CHROME <i>cut</i>	712.70	✓
5	1 PC BOOT LID LOGO <i>re</i>	101.60 -	
6	1 PC BOOTLID "HYBRID SYNERGY DRIVE" EMBLEM <i>new</i>	91.90 -	
7	2 PCS BOOT LID SIDE BLACK GARNISH <i>RH cut</i>	379.20 -	189.60
8	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	145.60 +	
9	1 PC REAR WINDSCREEN RUBBER WITH GLASS ASSY <i>new</i>	1,880.30	285
10	1 PC BOOT LID TRIM <i>Delhd</i>	669.30 -	
11	1 PC BOOT LID LOCK <i>Dented</i>	663.10	486
12	1 PC BOOT LID LOCK CHECKER new bent	55.60 -	
13	2 PCS BOOT LID SIDE CHECKER <i>new</i>	191.20 +	
14	1 PC BOOT LID HOLDING GARNISH <i>Delhd</i>	79.40	✓
15	1 PC BOOT LID RUBBER <i>cut</i>	367.90 -	
16	1 PC BOOT LID OPENER HANDLE <i>new</i>	299.10 +	
17	2 PCS BOOTLID SIDE SMALL STOPPER <i>new</i>	58.20 +	
18	1 PC TAIL LAMP - RH <i>cut</i>	1,318.70	781
19	1 PC REAR BUMPER TOP BUMPER RH <i>Delhd</i>	396.10 -	
20	1 PC TAIL LAMP LH <i>new</i>	1,318.70 +	
21	1 PC REAR PANEL <i>Dented</i>	735.70 -	
22	1 PC REAR PANEL TRIM <i>Delhd</i>	299.60 -	
23	1 PC SPARE TYRE PANEL <i>new</i>	825.20 +	
24	1 PC SPARE TYRE PANEL TRIM <i>new</i>	616.50 +	
25	1 PC SPARE TYRE TOP COVER <i>Delhd</i>	928.90	791
26	1 PC SPARE TYRE TOOL COVER <i>Delhd</i>	212.10 -	
27	1 PC REAR FENDER INNER TRIM RH <i>Delhd</i>	897.90	✓
28	1 PC REAR FENDER INNER TRIM LH <i>new</i>	897.90 +	
29	1 PC REAR BUMPER <i>Delhd</i>	1,080.10	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199

FAX: 68299247

ATTN: Motor Claim Department

Estimate No: EST2200171

Date: 02 Jun 2022

Veh Reg No: SMQ9915H

Make/Model: TOYOTA NOAH
HYBRID 1.8X CVT

Chasis No: ZWR800415199

Reg. Date: 13/12/2019

Your Ref No: SLB363A

Claim Type: Third Party

Accident Date: 01/06/2022

TP Veh Reg No: SLB363A

Estimate Repair Cost to Vehicle No :SMQ9915H

Quantity	Description	List Price	Amount
		SS	SS
30	2 PCS REAR BUMPER SIDE RETAINER <i>mc</i>	326.80	150
31	1 PC REAR BUMPER REFLECTOR - RH <i>mc</i>	78.90	2
32	1 PC REAR ANTENNA SENSOR <i>mc</i>	166.40	2
33	2 PCS REAR BUMPER LONG RETAINER <i>mc</i>	394.40	190
34	1 PC REAR BUMPER KEYLESS SENSOR <i>mc</i>	207.50	2
		18,984.50	
		Less 25%	4,746.13
			14,238.47
	Special Net		
35	1 PC BOOT LID BLACK LINING <i>mc</i>	100.00	60
36	1 PC REAR NUMBER PLATE <i>Best</i>	50.00	-
37	1 PC REVERSE CAMERA <i>Damaged</i>	480.00	✓
38	1 PC REAR WINDSCREEN SEAL <i>mc</i>	60.00	30
39	1 PC REAR WINDSCREEN SEALANT <i>mc</i>	60.00	30
40	1 SET BOOTLID TRIM CLIPS <i>mc</i>	80.00	30
41	1 SET REAR PANEL TIM CLIPS <i>mc</i>	60.00	20
42	1 SET REAR FENDER RH INNER TRIM CLIPS <i>mc</i>	80.00	30
43	1 SET REAR FENDER INNER TRIM LH CLIPS <i>mc</i>	80.00	4
44	1 SET REAR BUMPER CLIPS <i>mc</i>	60.00	30
45	1 SET REVERSE SENSORS <i>Damaged</i>	250.00	200
46	2 PCS REAR BUMPER STICKER <i>mc</i>	400.00	200
		1,760.00	1,760.00
	Labour		
47	1 TO CHECK WIRING	50.00	30
48	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00	X
49	1 TO REMOVE AND REFIT BOOTLID <i>Fittings</i>	80.00	✓
50	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
51	1 TO REMOVE AND REFIT VIDEO CAMERA	80.00	50
52	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	50
53	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199

FAX: 68299247

ATTN: Motor Claim Department

Estimate No: EST2200171

Date: 02 Jun 2022

Veh Reg No: SMQ9915H

Make/Model: TOYOTA NOAH
HYBRID 1.8X CVT

Chasis No: ZWR800415199

Reg. Date: 13/12/2019

Your Ref No: SLB363A

Claim Type: Third Party

Accident Date: 01/06/2022

TP Veh Reg No: SLB363A

Estimate Repair Cost to Vehicle No :SMQ9915H

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
54	1 TO REMOVE AND REFIT INNER TRIM	180.00	60
55	1 TO SPRAY PANEL SEALANT	100.00	60
56	1 (REAR) TO SPRAY PAINTING	1,400.00	1200
57	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00	1000
		4,050.00	4,050.00
	Total	SS 20,048.47	
	Add GST @ 7%	1,403.39	
	Total Amount Payable	SS 21,451.86	

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND FOUR HUNDRED FIFTY ONE AND CENTS EIGHTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

Supplementary: 154.35

AUTHORISED SIGNATURE

total: 12204.27

(CP/P)

Adrian Lij

H/s 06/06/22.

08 Days.

08 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER 5
SINGAPORE 038985

TEL: 68299199 FAX: 68299247
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 01/06/2022
TP Veh Reg No: SLB363A

Estimate No: EST2200171

Date: 12 Jul 2022

Veh Reg No: SMQ9915H

Make/Model: TOYOTA NOAH
HYBRID 1.8X CVT

Chasis No: ZWR800415199


Reg. Date: 13/12/2019

Your Ref No: SLB363A

Estimate Repair Cost to Vehicle No :SMQ9915H

Quantity	Description	List Price S\$	Amount S\$
Supplementary Parts to Repair			
1	1 PC REAR JACK BRACKET	205.80	✓
		205.80	
	Less 25%	51.45	154.35
Total			S\$ 154.35
GST Amount			S\$ 10.80
Total Amount Payable			S\$ 165.15

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

Supplementary : 154.35.