

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005411/EVY3E2

Date: 01/08/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00116322100
Claimant Vehicle No : GBH4368Y **Insured Vehicle No :** GBH8158K
Date of Loss: 05/04/2022 Nature of Claim: TP Claim No: SNM22D202356/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH4368Y**
Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25424617A
Reg. Date: 30/05/2018 (Man. Year: 2017) Chassis No: JN1MC2E26Z0008865
Colour: White Odometer: 153339 km
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,346.98	1,150.73	196.25	14.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	630.00	400.00	38.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,376.98	1,780.73	596.25	25.08
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,376.98	1,400.00	976.98	41.10
+ GST 7.00/7.00% (S\$)	166.39	98.00	68.39	41.10
Nett Amount (S\$)	2,543.37	1,498.00	1,045.37	41.10

INSPECTION

Date of Assignment: 01/07/2022
Date Inspected: 07/06/2022 Inspected At: Ethoz Automotive Solutions Ltd (HQ)
30, BUKIT BATOK CRESCENT
Singapore 658075
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Aug 2022)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH4368Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	510.50 FN	*510.50 FN
2	1		*FRONT BUMPER RETAINER LH	Broken	138.70 FN	*138.70 FN
3	1		*FRONT BUMPER CLIPS	Necessary	50.00 FN	*30.00 FN
4	1		*FOGLAMP GARNISH LH	Not Necessary	142.50 FN	*- FN
5	1		*FRONT CORNER PANEL LH (NPA)	Not Necessary	0.00 FN	*- FN
6	1		*HEADLAMP LH	Broken	410.50 FN	*410.50 FN
7	1		*STEP PANEL LH (NPA)	Not Necessary	0.00 FN	*- FN
8	1		*FRONT DOOR LH (NPA)	Not Necessary	0.00 FN	*- FN
9	1		*FRONT DOOR ADVERTISEMENT STICKER	Necessary	200.00 FS	*150.00 FS
10	1		*FRONT DOOR ROC STICKER LH	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	1,472.20	1,259.70
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	125.22	108.97
Total Parts (\$\$)	1,346.98	1,150.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	500.00	200.00
2	TO RESPRAY AFFECTED AREAS	New	500.00	400.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (\$)			1,030.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >