

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

13/6/2022

M/S INDIA INTERNATIONAL INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR NISSAN NV350 HR - SLT9984D

DOA : 06/06/2022

S/N	QTY	DESCRIPTION			
1	1 PC	FRT PANEL	\$	1326.70	X
2	1 PC	FRT LH CORNER PANEL	\$	577.80	
3	1 PC	FRT LH HEAD LAMP	\$	475.90	
4	1 PC	FRT GRILLE	\$	620.30	
5	1 PC	FRT GRILLE CHROME MLD	\$		X
6	1 PC	FRT GRILLE BADGE	\$	86.20	X
7	1 PC	FRT BUMPER	\$	1019.20	
8	10 PCS	FRT BUMPER CLIPS	\$	40.00	
9	1 PC	FRT BUMPER LH FOG LAMP COVER	\$	127.00	X
10	1 PC	FRT LH DOOR	\$	1156.00	
11	1 PC	FRT LH DOOR STEP GARNISH COVER	\$	65.60	
12	2 PCS	FRT LH DOOR HINGE	\$	84.80	X
13			\$	5579.50	
14			Disc -10%	-557.95	
15			\$	5021.55	
16		LABOUR CHARGE		680.00	450
17		SPRAY PAINTING		850.00	700
18		WIRING		35.00	20
19		TUFF COAT		120.00	50
20				380.00	180 s/n
				<u>7086.55</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not
14/6/22
2/5 #3600
3 days
whip? After up

not item
P-3495 80
102
3146.31
1400
454631
3637