


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 99500
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: FBQ8134G Yr Regn: 2019 Dec.
Type: M.Car / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha Sniper 150 C.C. 150
Colour: Green A/C: Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MH3460740Kd52637
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: M / S/Rim / STD A/Rim or
Tyre Size: F: 70/90R17
R: 2
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Maxxis
Front _____ Rear _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. _____ D.O.I. 8/6/22
Survey held at Bike Production
Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 5 Jun 2022

ASSESSMENT FOR REPAIR: YAMAHA SNIPER T150 - FBQ8134G

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front disk	\$115.00 x
1 pc	Front wheel axle	\$75.00 ?
1 pc	Right fork assembly	\$380.00 } #?
1 pc	Left fork assembly	\$380.00 }
1 pc	Front headlamp lower cover	\$105.00
1 pc	Headlamp lower assy	\$250.00 ?
1 pc	Front mudguard	\$85.00 cut
2 pcs	Steering stem bearing @ \$45.00	\$90.00 ?
1 pc	Steering stem bracket assembly	\$195.00 ?
1 pc	Gear pedal assembly	\$105.00 bt
1 pc	Left front footrest	\$65.00 bt
1 pc	Left front signal	\$75.00 cut
1 pc	Handle bar	\$125.00 ?
1 pc	Right fairing	\$105.00 cut
1 pc	Left fairing	\$105.00 de
2 pcs	Fairing stickers @ \$55.00	\$110.00 ner
1 pc	Right front signal	\$75.00 cut
1 pc	Brake pedal assy	\$75.00 dd
1 pc	Front black cover back	\$125.00 cut
1 pc	Front footrest holder assembly	\$145.00 bt
1 pc	Brake lever	\$45.00 cut
1 pc	Right balancer	\$45.00 nris
1 pc	Front cover labels	\$35.00 ner
1 pc	Top head cover	\$75.00 cut
1 pc	Front brake pump assembly	\$145.00 cut
1 pc	Front head inner black cover	\$125.00 ?
1 pc	Right rear side cover	\$105.00 cut - ena
1 pc	Right rear side cover sticker	\$45.00 nris
1 pc	Right front foot rest	\$65.00 del
1 pc	Right rear footrest	\$45.00 dd
1 pc	Right hand grip	\$45.00 cut
1 pc	Right view mirror	\$55.00 cut
1 pc	Exhaust assembly	\$485.00 dd
1 pc	Exhaust round cover	\$75.00 cut
1 pc	Exhaust long cover	\$45.00 cut
		<hr/>
		\$4,220.00
		<hr/>
		\$422.00
		<hr/>
		\$3,798.00
		<hr/>
		\$20.00 ner
1 pc	Front number plate	\$195.00 cut
1 pc	Top box	\$350.00 cut
1 pc	Front sport rim assy	

1)	Towing charges	\$100.00	2/
2)	Dismantle, replace, realign and adjust above damaged parts	\$700.00	300
4)	To knock, straighten chassis & body balancing	\$380.00	X
5)	To remove/refit, replace (if damage) check and straighten front fork tubes	\$180.00	120 ? photo.
6)	To remove/refit and balance front sport rim	\$90.00	30
7)	Spray painting	\$300.00	200
Total Estimate		<u>\$6,113.00</u>	

Note: The above estimate is subjected to the prevailing GST of 7%


For Bike Production Pte Ltd



Tanpin 9749 5749
WP' 8/6/22 @ 2pm
1/3 Resurvey after repair
Tanpin @ 1 hour
"3 days"

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: