

ASS. REC. BY:

REF:

CT2 / 22005417/Kny3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMK 9646

Yr Regn:

10 / 14

Type:

M. Car

M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c

1498

Colour

m. yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

87870

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMGK58501=X 201252

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

4

mm

L/Bal.

7

mm

L/Bal.

4

mm

D.O.A.

2 / 6 / 22

D.O.I.

20 / 6 / 2022

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/12 21/12 @ 3800 Cash (Red, \$1739, 31%)

Date/Time, File Pass to?



: Prel. Report

1) 31/123



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

3800

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 918J

Vehicle Details

Vehicle No.: SMK964G

Vehicle to be Exported: No

Intended Deregistration Date: 06 Jun 2022

Vehicle Make: HONDA

Vehicle Model: JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

Primary Colour: Yellow

Manufacturing Year: 2014

Engine No.: L15B31000080

Chassis No.: JHMGK5850FX201252

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$15,806.00

Original Registration Date: 15 Oct 2014

First Registration Date: 15 Oct 2014

Transfer Count: 1

Actual ARF Paid: \$5,806.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Oct 2024

PARF Rebate Amount: \$3,483.00

Intended COE Rebate Details

COE Expiry Date: 14 Oct 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10


QP Paid: \$64,841.00

COE Rebate Amount: \$15,269.00

Total Rebate Amount: \$18,752.00

The information contained herein is correct as at 06 Jun 2022

OK



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP CHINA
Policy No:	DMCVSNW00120592100	Date of Loss:	02/06/2022
Vehicle Reg. No.:	SMK964G	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NORHIDAYANA BINTE JABAR	Driver (Insured):	ISLAM MD ARIFUL
Make/Model:	HONDA JAZZ, 1.5 VTIR CVT ABS D/AIRBAG 2WD (A)	Vehicle Reg. Date:	15/10/2014
Vehicle Colour:	WHITE/YELLOW/ORANGE	Chassis No:	JHMGK5850FX201252
Engine No:	L15B31000080		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER EFILE REPORT		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not authorized
1/1/2022
Permy After Pay
Jky,*

COST OF CLAIMS

	Amount
Parts	2,569.00
Miscellaneous Items	160.00
Labour	2,810.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,539.00
+ GST 7.00% (S\$)	387.73
Nett Amount (S\$)	5,926.73

This claim is handled by: JUNE PHUA LIAN HUA

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jun 2022)
Parts: 144 HONDA JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMK964G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*220.00 F
2	1		*1 PC REAR BUMPR SIDE RETAINER LH	0.00	0.00	*14.00 F
3	1		*1 PC REAR BUMPER INNER SHIELD LH	0.00	0.00	*60.00 F
4	1		*1 PC REAR LH FENDER	0.00	0.00	*460.00 F
5	1		*1 PC REAR LH TRIANGE GLASS MOULDING	0.00	0.00	*30.00 F
6	1		*1 PC REAR LH DOOR	0.00	0.00	*470.00 F
7	1		*1 PC REAR LH DOOR FRAME STICKER	0.00	0.00	*15.00 F
8	1		*1 PC FRT LH DOOR	0.00	0.00	*510.00 F
9	1		*1 PC FR TLH DOOR FRAME STICKER	0.00	0.00	*30.00 F
10	1		*1 PC FRT LH OUTER HANDLE	0.00	0.00	*130.00 F
11	1		*1 PC FRT LH DOOR GLASS	0.00	0.00	*290.00 F
12	1		*1 PC LH SIDE SKIRT	0.00	0.00	*340.00 F
Total Parts (\$\$)						2,569.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No.	Qty	Particulars	Amount
1	1	1 PC FRT LH DOOR GLASS TINTED FILM	120.00
2	1	1 PC RER LH FENDER GLASS SEALANT	40.00
Sub Total (\$\$)			160.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	1) TO REMOVE AND REFIX REAR BUMPER & ATTACHMENTS, TAILLAMP, LH SIDE SKIRT, BOTH LH DOORS & ATTACHMENTS; CUT, WELD AND RENEW REAR LH FENDER, KNOCK AND REPAIR REAR H DOOR PILLAR AND RE-ALIGN TO SAME	New	1,100.00
2	2) TO PUTTY AND RESPRAY ON BOTH LH DOORS & PILLAR, SIDE MIRROR, LH SIDE SKIRT, REAR BUMPER, REAR LH FENDER AND ALL AFFECTED AREAS	New	1,300.00
3	3) TO REMOVE AND REFIX REAR LH FENDER TRIANGLE GLASS	New	50.00
4	4) TO REMOVE AND REFIX BOTH LH DOOR GLASS AND RESET CENTRAL LOCKING	New	120.00
5	5) TO REMOVE AND REFIX REAR SEAT, CARPET TO FACILITATE ON REPAIRS	New	120.00
6	6) TO RUSTPROOFING	New	120.00
Gross Labour Cost (\$\$)			2,810.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >