

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005418/TNY3Q2**Date:** 25/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00075662201
Claimant Vehicle No :	SLK3833T	Insured Vehicle No :	SMW4473S
Date of Loss:	31/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203852/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK3833T	Engine No:	CDN188055
Make & Model:	AUDI A4, 1.6 (A)	Chassis No:	WAUZZZ8K6BA137090
Reg. Date:	29/04/2011 (Man. Year: 2011)	Odometer:	257481 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,265.70	8,291.69	14,974.01	64.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	1,610.00	2,900.00	64.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,775.70	9,901.69	17,874.01	64.35
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	27,775.70	7,900.00	19,875.70	71.56
+ GST 8.00/8.00% (S\$)	2,222.06	632.00	1,590.06	71.56
Nett Amount (S\$)	29,997.76	8,532.00	21,465.76	71.56

INSPECTION

Date of Assignment:	11/06/2022	
Date Inspected:	09/06/2022 Inspected At:	8 KAKI BUKIT AVE 4 #01-50, PREMIER @ KAKI BUKIT SINGAPORE 415875 Repairer: REVO PRIME (HQ)
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2023)
Parts:	143	AUDI A4 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3833T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	3,642.00 FL	*1,937.90 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	167.00 FL	*108.15 FL
3	1		*BOOTLID A4 EMBLEM	Necessary	113.00 FL	*105.00 FL
4	1		*BOOTLID 2.0T EMBLEM	Necessary	132.00 FL	*108.00 FL
5	1		*BOOTLID RH LAMP	Not Necessary	1,032.00 FL	*- FL
6	1		*BOOTLID LH LAMP	Not Necessary	1,032.00 FL	*- FL
7	1		*BOOTLID LOCK	Not Necessary	301.00 FL	*- FL
8	1		*BOOTLID LOCK CATCH	Not Necessary	98.00 FL	*- FL
9	1		*BOOTLID RH NUMBER PLATE LAMP	Not Necessary	94.00 FL	*- FL
10	1		*BOOTLID LH NUMBER PLATE LAMP	Not Necessary	94.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	2,996.00 FL	*2,287.00 FL
12	1		*REAR BUMPER CLIPS	Necessary	120.00 FL	*30.00 FL
13	1		*REAR BUMPER LOWER GARNISH	Deformed	451.00 FL	*450.00 FL
14	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Necessary	278.00 FL	*- FL
15	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Not Working	278.00 FL	*185.00 FL
16	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Not Working	278.00 FL	*185.00 FL
17	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Necessary	278.00 FL	*- FL
18	4		*REAR BUMPER REVERSE SENSOR SEALS	Necessary	112.00 FL	*112.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	1,151.00 FL	*985.00 FL
20	1		*REAR BUMPER RH SIDE UPPER BRACKET	Not Necessary	43.00 FL	*- FL
21	1		*REAR BUMPER RH SIDE LOWER BRACKET	Not Necessary	61.00 FL	*- FL
22	1		*REAR BUMPER LH SIDE UPPER BRACKET	Cracked	43.00 FL	*43.00 FL
23	1		*REAR BUMPER LH SIDE LOWER BRACKET	Cut	61.00 FL	*61.00 FL
24	1		*REAR BUMPER TOWING COVER	Not Necessary	67.00 FL	*- FL
25	1		*RH TAILLAMP ASSY	Cracked	1,231.00 FL	*900.97 FL
26	1		*LH TAILLAMP ASSY	Cracked	1,231.00 FL	*900.97 FL
27	1		*END PANEL	Repair	731.00 FL	*- FL
28	1		*END PANEL INNER GARNISH	Deformed	267.00 FL	*267.00 FL
29	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	60.00 FL	*20.00 FL
30	1		*REAR COMPARTMENT PANEL TOP COVER BOARD	Not Necessary	786.00 FL	*- FL
31	1		*REAR FENDER RH INNER TRIM BOARD	Not Necessary	811.00 FL	*- FL
32	1		*REAR FENDER LH INNER TRIM BOARD	Not Necessary	811.00 FL	*- FL
33	1		*REAR RH EXHAUST SILENCER	Not Necessary	1,423.00 FL	*- FL
34	1		*REAR RH EXHAUST SILENCER GASKET	Not Necessary	55.00 FL	*- FL
35	1		*REAR LH EXHAUST SILENCER	Not Necessary	1,423.00 FL	*- FL
36	1		*REAR LH EXHAUST SILENCER GASKET	Not Necessary	55.00 FL	*- FL
37	1		*REAR BUMPER LOWER SPOILER (AFTER MARKET)	Not Necessary	2,400.00 FS	*- FS
38	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,356.00	8,725.99
- List Item Discount on L Items 5.00/5.00% (\$\$)	1,090.30	434.30
Total Parts (\$\$)	23,265.70	8,291.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHAGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,600.00	700.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,400.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	30.00
5	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	100.00	60.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
7	REMOVE AND REPLACE REAR INNER TRIM ,GARNISH AND BOARDS TO ASSIST REPAIR	New	320.00	60.00
8	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	320.00	0.00
9	RESET AND DIAGNOSE ELECTRONIC CONTROL UNIT AND FAULT CODE AFTER REPAIRS	New	450.00	0.00
Gross Labour Cost (\$\$)			4,510.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >