

# REVO PRIME PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 202021344Z

Company Reg No: 201929175W

## Repair Estimate

Vehicle number: SLK3833T

Make & Model: Audi A4

Chassis number: WAUZZZ8K6BA137090

Date of survey: \_\_\_\_\_

Name of surveyor: \_\_\_\_\_

Contacts: \_\_\_\_\_

| No. | Description of spare parts                                                      | Qty  | Amount S\$  |
|-----|---------------------------------------------------------------------------------|------|-------------|
| 1   | Bootlid <span style="float: right;">1937.90</span>                              | 1    | \$ 3,642.00 |
| 2   | Bootlid centre emblem <span style="float: right;">108.15</span>                 | 1    | \$ 167.00   |
| 3   | Bootlid "A4" emblem <span style="float: right;">105</span>                      | 1    | \$ 113.00   |
| 4   | Bootlid "2.0T" emblem <span style="float: right;">108</span>                    | 1    | \$ 132.00   |
| 5   | Bootlid RH lamp                                                                 | 1    | \$ 1,032.00 |
| 6   | Bootlid LH lamp                                                                 | 1    | \$ 1,032.00 |
| 7   | Bootlid lock                                                                    | 1    | \$ 301.00   |
| 8   | Bootlid lock catch                                                              | 1    | \$ 98.00    |
| 9   | Bootlid RH number plate lamp                                                    | 1    | \$ 94.00    |
| 10  | Bootlid LH number plate lamp                                                    | 1    | \$ 94.00    |
| 11  | Rear bumper <span style="float: right;">2287 <del>1891</del></span>             | 1    | \$ 2,996.00 |
| 12  | Rear bumper clips <span style="float: right;">30</span>                         | 1    | \$ 120.00   |
| 13  | Rear bumper lower garnish <span style="float: right;">450 <del>180</del></span> | 1    | \$ 451.00   |
| 14  | Rear bumper RH side reverse sensor                                              | 1    | \$ 278.00   |
| 15  | Rear bumper RH centre reverse sensor <span style="float: right;">185</span>     | 1    | \$ 278.00   |
| 16  | Rear bumper LH centre reverse sensor <span style="float: right;">185</span>     | 1    | \$ 278.00   |
| 17  | Rear bumper LH side reverse sensor                                              | 1    | \$ 278.00   |
| 18  | Rear bumper reverse sensor seals                                                | 4    | \$ 112.00   |
| 19  | Rear bumper reinforcement <span style="float: right;">985 <del>598</del></span> | 1    | \$ 1,151.00 |
| 20  | Rear bumper RH side upper bracket                                               | 1    | \$ 43.00    |
| 21  | Rear bumper RH side lower bracket                                               | 1    | \$ 61.00    |
| 22  | Rear bumper LH side upper bracket                                               | 1    | \$ 43.00    |
| 23  | Rear bumper LH side lower bracket                                               | 1    | \$ 61.00    |
| 24  | Rear bumper towing cover                                                        | 1    | \$ 67.00    |
| 25  | RH taillamp assy <span style="float: right;">900.97 <del>800.97</del></span>    | 1    | \$ 1,231.00 |
| 26  | LH taillamp assy <span style="float: right;">900.97 <del>800.97</del></span>    | 1    | \$ 1,231.00 |
| 27  | End panel                                                                       | 1    | \$ 731.00   |
| 28  | End panel inner garnish                                                         | 1    | \$ 267.00   |
| 29  | End panel inner garnish clips                                                   | 1set | \$ 60.00    |
| 30  | Rear compartment panel top cover board                                          | 1    | \$ 786.00   |
| 31  | Rear fender RH inner trim board                                                 | 1    | \$ 811.00   |
| 32  | Rear fender LH inner trim board                                                 | 1    | \$ 811.00   |
| 33  | Rear RH exhaust silencer                                                        | 1    | \$ 1,423.00 |

|    |                                 |   |             |
|----|---------------------------------|---|-------------|
| 34 | Rear RH exhaust silencer gasket | 1 | \$ 55.00    |
| 35 | Rear LH exhaust silencer        | 1 | \$ 1,423.00 |
| 36 | Rear LH exhaust silencer gasket | 1 | \$ 55.00    |
|    |                                 |   |             |
|    |                                 |   |             |
|    |                                 |   |             |

7251.34

|               |    |           |
|---------------|----|-----------|
|               | \$ | 21,806.00 |
| Parts less 5% | \$ | 1,090.30  |
| Total         | \$ | 20,715.70 |

| No. | Special Nett Items                       |   | Amount S\$  |
|-----|------------------------------------------|---|-------------|
| 1   | Rear bumper lower spoiler (after market) | 1 | \$ 2,400.00 |
| 2   | End panel joint sealant                  | 1 | \$ 80.00    |
| 3   | Rear number plate                        | 1 | \$ 70.00    |
|     |                                          |   |             |
|     |                                          |   |             |

|        |    |          |
|--------|----|----------|
| Total: | \$ | 2,550.00 |
|--------|----|----------|

[illegible]

700

30

30.

63

30

60.

kmn

425

1610

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)  
Working days: \_\_\_\_\_

Total: \$ 4,510.00

Spare Parts: \$ 20,715.70  
Special Nett: \$ 2,550.00  
Labour: \$ 4,510.00

Total Amount: \$ 27,775.70

Taufik 97475747  
WP' 9/6/22 @ 130pm  
To check consistency of accident  
& part prices  
L/S Resurvey after repair  
taufik @ hantawon  
6 days

~~7251.34~~ 9901.69

40

1610

~~8901.34~~ 7921.35

~~6157100~~ LS: \$7900

6 days  
#

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: