

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 07.06.2022

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : GW2509H
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 06.06.2022
TIME OF ACCIDENT : 12:00HRS

Vern.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,370.00	\$ 1,370.00
2	TAILGATE HINGE <i>Bent</i>	4	\$ 165.00	\$ 660.00
3	TAILGATE SIDE LOCK <i>Bent</i>	2	\$ 125.00	\$ 250.00
4	TAILGATE STOPPER RUBBER <i>Missing</i>	2	\$ 35.00	\$ 70.00
5	TAILGATE STOPPER BRACKET <i>Bent</i>	2	\$ 175.00	\$ 350.00
6	SIDE GATE <i>Dented</i>	2	\$ 1,968.90	\$ 3,937.80
7	SIDE GATE SAFETY LOCK <i>Bent</i>	2	\$ 132.10	\$ 264.20
8	TAIL LAMP <i>Cracked</i>	2	\$ 245.00	\$ 490.00
9	TAIL LAMP SUPPORT BRACKET <i>Bent</i>	2	\$ 185.00	\$ 370.00
10	REAR END PENEL <i>Dented</i>	1	\$ 1,245.00	\$ 1,245.00
11	REAR CARGO BED <i>Repair</i>	1	\$ 2,899.30	\$ 2,899.30

5548.10

4461.07

TOTAL PRICE \$ 11,906.30
LESS 25% \$ 2,976.58
SUB TOTAL PRICE \$ 8,929.73

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE COMPANY STICKER (SPECIAL TYPE) <i>New</i>	1	\$ 380.00	\$ 380.00
3	TAIL GATE '70KM/H' STICKER <i>2 New</i>	1	\$ 40.00	\$ 40.00
4	TAIL GATE '13PSX' STICKER	1	\$ 850.00	\$ 850.00
5	SIDE GATE COMPANY STICKER (SPECIAL TYPE) <i>NEC</i>	2	\$ 580.00	\$ 1,160.00
6	REVERSE SENSOR (SET) <i>Not in</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 2,700.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : GW2509H
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 06.06.2022
TIME OF ACCIDENT : 12:00HRS

1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,800.00	1000
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	1000
3	REMOVE AND REFIX REAR RAILING	\$ 350.00	200
4	REMOVE AND REFIX REVERSE SENSOR	\$ 80.00	X
5	REMOVE AND REFIX REAR CARGO BED	\$ 650.00	X
6	REAR CHASSIS ALIGHMENT	\$ 250.00	X

TOTAL \$ 4,730.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,629.73
TOTAL LABOUR COST : \$ 4,730.00
TOTAL REPAIR COST : \$ 16,359.73

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian Lij
L/S 07/06/22.

07 Days.

Total: 7711.07

L/S : 4.2K (Nett Value) ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: