



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III22001271/Vqy3e2-1	
			Date: 14/09/2022	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 4527Z	Veh. Inspected	PC 9917R	
Policy No.	D21MFL0000447_01	Coverage (\$)	0.00	
Claim No.	MFL2022D0000707	Excess (\$)	0.00	
Assign From	CARINE KEK	Assign Date	07/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	GDH2232002309	Colour	ORANGE	
Odometer	25109 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	DUNLOP	6 mm	
L/H Front Tyre	195/80 R15	DUNLOP	6 mm	
R/H Rear Tyre	195/80 R15	DUNLOP	6 mm	
L/H Rear Tyre	195/80 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2022	Inspection Date	10/02/2022	
Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	