



VICOM LTD

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No: 198100320K

TAX INVOICE

COMFORTDELGRO ENGINEERING PTE LTD
#205 Braddell Road
Blk C Ext 1 3rd Level
Singapore 579701

ATTN : MOTOR CLAIMS DEPT.

VEHICLE No. : SHC7708K
ACCIDENT DATE : 16/10/2021
CLAIM No. : 305491109
INSURED VEH.No: QX1222S

GST REG No. : M9-0000652-A
CUSTOMER ID : VACC0013
INVOICE No. : LY013659
INVOICE DATE : 01/11/2021
PAYMENT TERM : 30 Days Credit

DESCRIPTION	QTY	UNIT PRICE (SG\$)	AMOUNT (SG\$)
Photographs	6	1.00	\$ 6.00
Transportation	1	50.00	\$ 50.00
VAC Assessment Fee	1	125.00	\$ 125.00

REMARKS	GROSS AMOUNT	\$ 181.00
CCPL	GST @ 7%	\$ 12.67
	INVOICE AMOUNT	\$ 193.67

This is a computer generated TAX INVOICE

No signature required

Cheque should be made payable to 'VICOM LTD'.

Sin Ming

385 Sin Ming Drive Singapore 575718
Tel: (65) 6455 5358 Fax: (65) 6455 8638

Bukit Batok

511 Bukit Batok St 23 Singapore 659545
Tel: (65) 6560 3312 Fax: (65) 6569 0722

Kaki Bukit

23 Kaki Bukit Ave 4 Singapore 415933
Tel: (65) 6741 6697 Fax: (65) 6749 2305

COMFORTDELGRO ENGINEERING PTE LTD
#205 Braddell Road
Blk C Ext 1 3rd Level
Singapore 579701



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION

VAC Ref. No.	: 570704	Claim No.	: 305491109
Accident Date	: 16/10/2021	Claim Type	: THIRD PARTY
Assignment Date	: 19/10/2021	Policy No.	:
Survey Date	: 19/10/2021	Finalised Dt.:	
Survey Report Date	: 30/10/2021		

VEHICLE PARTICULARS

Vehicle No.	: SHC7708K	Chassis No.	: KMHC851CVLU180858
Registration Date	: 22/10/2019	Engine No.	: OBSCURED
Make	: HYUNDAI	Engine Cap.	: 1580 CC
Model	: IONIQ (G3)	Transmission	: AUTO
		Colour	: YELLOW

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	:		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	195/60R16	WESTLAKE	6
FRONT LH	195/60R16	WESTLAKE	6
REAR RH	195/60R16	WESTLAKE	6
REAR LH	195/60R16	WESTLAKE	6

SURVEY CONDUCTED AT

59 Loyang Drive
Singapore 508969

REMARKS

[1] Workshop Estimate : S\$ 1,746.12
[2] Our Adjustment : S\$ 1,021.00
[3] Repair Period : 2 days
[4] We have not authorised repairs. This survey was carried out on without prejudice basis.

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Bumper	Repair	459.40	0.00
2	1	Rear Bumper Centre Moulding	Snapped	451.25	451.25
3	10	Rear Bumper Clips	Reuse	22.00	0.00
			Subtotal	: 932.65	451.25
			Less 20 %	186.53	90.25
			TOTAL	: 746.12	361.00
SPECIAL NETT ITEM					
1	1	Reverse Sensor	Reuse	180.00	0.00
			TOTAL	: 180.00	0.00
			TOTAL FOR SPARE PARTS	: 926.12	361.00

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges	400.00	350.00
2	Spray painting charges	300.00	250.00
3	Remove/ refix reverse sensor	120.00	60.00
TOTAL FOR LABOUR AND SPRAY PAINTING		820.00	660.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	926.12	361.00
TOTAL FOR LABOUR AND SPRAY PAINTING	820.00	660.00
TOTAL REPAIR COST	1746.12	1021.00

SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$1,746.12. We adjusted it to S\$1,021.00 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$1,021.00.

The repairs would require a period of 2 working days.



Kamarudin Abdul Kadir
for VICOM Ltd



VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7708K ACCIDENT DATE : 16/10/2021

