PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ACCIDENT REPAIRS **ESTIMATE**

: UBI ROAD 1 WORKSHOP : 6366 2323 **CONTACT NO** : 6841 1183 FAX NO

: PA/TP/0470/2022/JT REFERENCE

7-Jun-22 DATE 27755 WIP

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 8/6/22

YOUR INSURED VEH NO: SMZ 4640 K

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120 Attn: Motor Claims Dept

TELEPHONE

Tel: 6880 4602 - Fax: 6880 4838

: MR LIM RUI DUAN IVAN (LIN RUIDUAN IVAN) **OWNER'S NAME**

BLK 13 FERNVALE LANE ADDRESS

#02-08

SINGAPORE 797498 : HP +65 96403208 THIRD PARTY CLAIM TYPE OF CLAIM

7210150876 **POLICY NO** SND 2274 B **VEHICLE NO**

AUDI Q3 1.4 TFSI S TRONIC MODEL CODE

14/12/2021 MODEL YEAR CZD C50066 **ENGINE NO**

WAUZZZF3XM1156949 **CHASSIS NO**

MILEAGE DATE IN

: JOHNNY BOO / ALLAN WU **ESTIMATED BY**

: 3-Jun-22 ACCIDENT DATE ALONG CTE PLACE OF ACCIDENT





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 2274 B

S/N	NATURE OF JOBS		CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	\$ 360.00	//
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,600.50	500/
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.		\$ 2,000.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 4,152.00	





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2274 B

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS	
1	REAR BUMPER Deformed	1	\$	1,738.00	1,390.40	
2	REAR BUMPER FIXING PARTS He M	1	\$	220.00 -	220.00 +	
3	REAR BUMPER SPOILER Let	1	\$	510.00	510.00 408.00	
4	REAR BUMPER TOWING EYE	1	\$	48.00 📉		
5	REAR BUMPER BRACKET	1	\$	53.00 -	53.00 >	
6	BOOT LID CONTROL UNIT	1	\$	454.00 >		
7	TAILGATE SENSOR LINE	1	\$	228.00 🗡		
8	AERIAL FOR KESSY	1	\$	79.00	r	
9	REAR LIGHT REFLECTOR - LH / RH WHO M	2	\$	92.00		
10	REAR BUMPER REINFORCEMENT BEAM	1	\$	693.00		
11	REAR BUMPER HOLDING STRAP - CENTER	1	\$	120.00		
12	REAR BUMPER GUIDE SECTION - LH / RH	2	5	142.00	K .	
13	REAR PARKING AID SENSOR	2	\$	530.00	+	
14	REAR PARKING AID SENSOR SEAL RING	4	\$	10.00	+	
15	REAR WHEEL ARCH COVER - LH / RH HEL	2	\$	566.00	452.00	
16	SUNDRIES X		\$	350.00×	NN	
	TOTAL SPARE PARTS	:	\$	5,833.00		
	TOTAL LABOUR CHARGES	;	\$	4,152.00		
	GRAND TOTAL	:	\$	9,985.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.

* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian L

SURVEYED DATE
AUTHORISED DATE

: 68 06 22.

EXCESS COST

:

LIABILITY REMARKS :

All Arthorsed, 03 Pays.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO BODY REPAIR MANAGER ALLAN WU CLAIMS CONSULTANT