

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0470/2022/JT
DATE : 07-Jun-22
WIP : 27755

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 8/6/22

YOUR INSURED VEH NO : SMZ 4640 K

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

3 days - ok - Jy - 4 Aug 22

OWNER'S NAME : MR LIM RUI DUAN IVAN (LIN RUIDUAN IVAN)
ADDRESS : BLK 13 FERNVALE LANE
#02-08
SINGAPORE 797498
TELEPHONE : HP +65 96403208
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210150876
VEHICLE NO : **SND 2274 B**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 14/12/2021
ENGINE NO : CZD C50066
CHASSIS NO : WAUZZZF3XM1156949
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 03-Jun-22
PLACE OF ACCIDENT : ALONG CTE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 2274 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$	500.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.	\$	2,000.00	\$	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 4,152.00	\$	1,602.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2274 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,738.00	\$ 1,390.40
2	REAR BUMPER FIXING PARTS	1	\$ 220.00	
3	REAR BUMPER SPOILER	1	\$ 510.00	\$ 408.00
4	REAR BUMPER TOWING EYE	1	\$ 48.00	
5	REAR BUMPER BRACKET	1	\$ 53.00	
6	BOOT LID CONTROL UNIT	1	\$ 454.00	
7	TAILGATE SENSOR LINE	1	\$ 228.00	
8	AERIAL FOR KESSY	1	\$ 79.00	
9	REAR LIGHT REFLECTOR - LH / RH	2	\$ 92.00	
10	REAR BUMPER REINFORCEMENT BEAM	1	\$ 693.00	
11	REAR BUMPER HOLDING STRAP - CENTER	1	\$ 120.00	
12	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 142.00	
13	REAR PARKING AID SENSOR	2	\$ 530.00	
14	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00	
15	REAR WHEEL ARCH COVER - LH / RH	2	\$ 566.00	\$ 452.00
16	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 5,833.00	\$ 2,250.40
TOTAL LABOUR CHARGES			\$ 4,152.00	\$ 1,602.00
GRAND TOTAL			\$ 9,985.00	\$ 3,852.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-27/07/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT