



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref:	CS/TP22005430/Uny3e2
BLK 1 KAKI BUKIT AVE 6			Date:	13/07/2022
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE				
417883				
ON BEHALF OF LIM THIAM GUAN			Code:	TP149
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.		Veh. Inspected	SMS 9933U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	08/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	LEXUS ES300H (A)	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTHBW1GG902118003	Colour	GREY	
Odometer	154169 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/06/2022	Inspection Date	08/06/2022	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	