

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 06.06.22

Undercarriage
photos ??

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SKU2278L
MODEL : BMW 318i
DATE OF ACCIDENT : 05.06.22
TIME OF ACCIDENT : 19:45HRS

WBAPF72050A794276.
Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehd</i>	1	\$ 1,069.10	\$ 1,069.10
2	REAR BUMPER SIDE RETAINER <i>LH Rgd.</i>	2	\$ 95.00	\$ 190.00
3	REAR BUMPER SIDE BRACKET <i>NE nec</i>	1	\$ 126.70	\$ 126.70
4	REAR WINDSCREEN MOULDING TOP <i>3MP</i>	1	\$ 95.00	\$ 95.00
5	REAR WINDSCREEN MOULDING SIDE <i>1hr</i>	2	\$ 86.00	\$ 172.00
6	REAR FENDER LH <i>Repair</i>	1	\$ 1,426.00	\$ 1,426.00
7	REAR FENDER COWLING LH <i>xhr nec</i>	1	\$ 429.65	\$ 429.65
8	REAR WHEEL RIM LH <i>Cat</i>	1	\$ 1,120.00	\$ 1,120.00
9	REAR ABS SENSOR LH <i>xhr nec</i>	1	\$ 327.75	\$ 327.75
10	REAR LOWER ARM LH <i>But</i>	1	\$ 979.65	\$ 979.65
11	REAR UPPER ARM LH <i>But</i>	1	\$ 784.55	\$ 784.55
12	REAR KNUCKLE ARM LH <i>But</i>	1	\$ 1,248.70	\$ 1,248.70
13	REAR SHOCK ABSORBER LH <i>Ren</i>	1	\$ 694.45	\$ 694.45
14	REAR LINKAGE LH <i>xhr nec</i>	1	\$ 195.00	\$ 195.00
15	REAR WHEEL HUP LH <i>Rgd</i>	1	\$ 298.35	\$ 298.35
16	REAR WHEEL HUP BEARING LH <i>Rgd.</i>	1	\$ 199.65	\$ 199.65

3370.10 SN: 850
3201.59

TOTAL PRICE \$ 9,356.55
LESS 5% \$ 467.83
SUB TOTAL PRICE \$ 8,888.72

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER SIDE SKIRT CLIP LH (SET) <i>xhr nec</i>	1	\$ 100.00	\$ 100.00
2	REAR WINDSCRREN SEALANT <i>xhr nec</i>	1	\$ 80.00	\$ 80.00
3	REAR WINDSCREEN INNER SHIELD <i>Ren</i>	1	\$ 80.00	\$ 80.00
4	REAR FENDER COWLING CLIP LH (SET) <i>Ren</i>	1	\$ 80.00	\$ 80.00
5	REAR WHEEL TYRE LH <i>Ren</i>	1	\$ 480.00	\$ 480.00
6	BRAKE OIL <i>Ren</i>	1	\$ 60.00	\$ 60.00

TOTAL \$ 880.00

✓
85
+
+
+
+
+
+
650(sw).
+
2 395
2 304
2 1009.
+
+
2
2

50
50

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKU2278L**
 MODEL : BMW 318i
 DATE OF ACCIDENT : 05.06.22
 TIME OF ACCIDENT : 19:45HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	500
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	500
3	TUFF COAT	\$ 250.00	40
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	X.
5	WIRING CHECK	\$ 250.00	30
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 160.00	X.
9	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	220
10	TO PRESS REAR WHEEL BEARING	\$ 80.00	X
11	FOUR WHEEL ALIGNMNET	\$ 120.00	80
12	RESET ABS LIGHT	\$ 350.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

1170

TOTAL \$4,880.00

TOTAL PARTS COST : \$ 9,768.72
 TOTAL LABOUR COST : \$ 4,880.00
 TOTAL REPAIR COST : \$ 14,648.72

Adrian Lj
 h/s 07/06/22.

05 Days

total: 5271.59

L/S: 4.2k

4.2k

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: