

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0467/2022/JT
DATE : 7-Jun-22
WIP : 27490

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/6/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS DEBORAH KHOO WEN SHI
ADDRESS : 2 GOLDHILL DRIVE
SINGAPORE 308951
TELEPHONE : HP +65 91890617
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100478645-05
VEHICLE NO : SLF 672 L
MODEL CODE : AUDI A1 SB 1.0 TFSI
MODEL YEAR : 11/8/2016
ENGINE NO : CHZ 102481
CHASSIS NO : WAUZZZ8X2GB113544
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jun-22
PLACE OF ACCIDENT : ALONG PIE TOWARDS ENG NEO EXIT

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 672 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X . X
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00	X. X
3	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	? X
4	TO DISMANTLE AND RENEW FRONT BUMPER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,500.00	500
5	TO RESPRAY FRONT BUMPER.	\$ 900.00	550
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	240
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192.
TOTAL LABOUR CHARGES		: \$ 9,464.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 672 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>torn</i>	1	\$ 1,738.00	✓ 1390.4
2	FRONT BUMPER FIXING PART <i>new</i>	1	\$ 259.00	+
3	FRONT BUMPER CLOSING ELEMENT <i>torn</i>	1	\$ 187.00	✓ 149.20
4	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 452.00	+
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 219.00	+
6	LOCK CARRIER <i>new</i>	1	\$ 1,137.00	+
7	RADIATOR COOLANT <i>new</i>	6	\$ 282.00	+
8	RADIATOR SEAL - LOWER <i>new</i>	1	\$ 29.00	+
9	NOISE INSULATION <i>torn</i>	1	\$ 355.00	✓ 284
10	UNDERBODY TRIM <i>new</i>	1	\$ 237.00	+
11	FRONT WHEEL HOUSING LINER - RH	1	\$ 183.00	+
12	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>3rd</i>	1	\$ 42.00	+
13	ALUMINIUM RIM <i>lit</i>	1	\$ 1,303.00	✓ 1042.40
14	RUBBER VALVE <i>new</i>	1	\$ 4.00	+, nn
15	SUSPENSION SUBFRAME ASSEMBLY CARRIER ?	1	\$ 1,143.00	? x nn
16	TRACK CONTROL ARM - RH ?	1	\$ 335.00	? x nn
17	FRONT WHEEL BEARING HOUSING BRAKE CARRIER - RH ?	1	\$ 533.00	? x nn
18	SUSPENSION GUIDE JOINT - RH ?	1	\$ 126.00	? x nn
19	ANTI-ROLL BAR ?	1	\$ 234.00	? x nn
20	COUPLING ROD ?	1	\$ 90.00	? x nn
SUB TOTAL SPARE PARTS		:	\$ 8,888.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 672 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEELHUB BEARING ?	1	\$ 487.00	? x nn
22	GAS SHOCK ABSORBER ?	1	\$ 418.00	? x nn
23	DRIVE SHAFT - RH <i>item</i>	1	\$ 2,161.00	x nn
24	STEERING GEAR TRACK RODS <i>x item</i>	1	\$ 2,824.00	x nn
25	TRACK ROD ?	1	\$ 91.00	? x nn
26	TIE ROD END - RH ?	1	\$ 122.00	? x nn
27	RHS FRONT TYRE <i>Punctured</i>	S/N	TBC 330	✓
28	SUNDRIES ?		\$ 600.00	? x nn
TOTAL SPARE PARTS		:	\$ 15,591.00	
TOTAL LABOUR CHARGES		:	\$ 9,464.00	
GRAND TOTAL		:	\$ 25,055.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian Lij
: 07/06/22.
:
:
:
: Not Authorised, 04 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: