

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22005457/ENY3E2

Date: 28/07/2022

REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPMF1000000510
Claimant Vehicle No :	GBF7831S	Insured Vehicle No :	SME8054L
Date of Loss:	19/05/2022	Nature of Claim:	TP
		Claim No:	C88AISCL2022-0004FR-SME8054L

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF7831S	Engine No:	R06A1859813
Make & Model:	SUZUKI EVERY, 658cc GA (A)	Chassis No:	DA17V170424
Reg. Date:	10/03/2017 (Man. Year: 2016)	Odometer:	155913 km
Colour:	White		
Engine Capacity:	658 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	155 R12C	Rear Tyre Size:	155 R12C
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,678.55	1,860.60	2,817.95	60.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,290.00	1,770.00	57.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,738.55	3,150.60	4,587.95	59.29
Approved Total (Overridden) (\$\$)		2,500.00		
(\$\$)	7,738.55	2,500.00	5,238.55	67.69
+ GST 7.00/7.00% (\$\$)	541.70	175.00	366.70	67.69
Nett Amount (\$\$)	8,280.25	2,675.00	5,605.25	67.69

INSPECTION

Date of Assignment:	08/06/2022	
Date Inspected:	13/06/2022	Inspected At: Mitsubishi HC Capital Asia Pacific Pte Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Jul 2022)	
Parts:	N/A	SUZUKI EVERY 658cc GA (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF7831S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,416.00 FL	*899.00 FL
2	1		*TAILGATE HINGE RH	Not Necessary	65.00 FL	*- FL
3	1		*TAILGATE HINGE LH	Not Necessary	65.00 FL	*- FL
4	1		*TAILGATE INNER BOARD	Not Necessary	120.00 FL	*- FL
5	1		*TAILGATE RUBBER	Not Necessary	220.00 FL	*- FL
6	1		*TAILGATE LOCK	Not Necessary	150.00 FL	*- FL
7	1		*REAR BUMPER	Broken	840.00 FL	*511.00 FL
8	1		*REAR BUMPER SIDE RETAINER RH	Broken	36.00 FL	*36.00 FL
9	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	36.00 FL	*- FL
10	1		*TAILLAMP RH	Broken	285.00 FL	*285.00 FL
11	1		*END PANEL	Repair	380.00 FL	*- FL
12	1		*END PANEL TOP GARNISH	Not Necessary	130.00 FL	*- FL
13	1		*TAILGATE EMBLEM	Necessary	45.00 FL	*45.00 FL
14	1		*REAR RH FENDER	Repair	655.00 FL	*- FL
15	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	120.00 FL	*60.00 FL
16	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*40.00 FS
17	1		*REAR LICENCE PLATE	Not Necessary	45.00 FS	*- FS
18	1		*REAR LICENSE PLATE BRACKET	Not Necessary	60.00 FS	*- FS
19	10		*END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
20	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*70KM STICKER	Necessary	70.00 FS	*25.00 FS
22	1		*6 PAX STICKER	Necessary	70.00 FS	*25.00 FS
23	1		*ADVERTISEMENT STICKER	Necessary	400.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,363.00	2,136.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	684.45	275.40
Total Parts (\$\$)	4,678.55	1,860.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT, CUT, WELD, RE-ALIGN & REPLACE DAMAGED PARTS OF REAR AFFECTED AREA	New	1,000.00	400.00
2	PUTTY, BLEND AND SPRAY PAINT ON REAR AFFECTED AREAS	New	1,200.00	600.00
3	CHECK WIRING, RE-ALIGN HEADLAMPS & TAILLAMPS, ENSURE PROPER FUNCTIONING	New	80.00	30.00
4	REMOVE AND REPLACE REAR WINDSCREEN TO FACILITATE REPAIR	New	180.00	120.00
5	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	150.00	30.00
6	REMOVE AND REINSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING WORK	New	150.00	30.00
7	DISMANTLE AND TRANSFER BOOT LID / TAILGATE FITTINGS & MECHANISMS TO NEW BOOT LID / TAILGATE	New	180.00	50.00
8	CONDUCT WATER SEEPAGE TEST	New	120.00	30.00
Gross Labour Cost (\$\$)			3,060.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >