

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22005463/VVY3M4**Date:** 24/08/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP315738
Claimant Vehicle No :	SH9418C	Insured Vehicle No :	SDN1225R
Date of Loss:	08/06/2022	Nature of Claim:	TP
		Claim No:	MPC03477

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9418C	Engine No:	D4FDGU625133
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU098197
Reg. Date:	11/01/2017 (Man. Year: 2016)	Odometer:	675307 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	206/60 R16	Rear Tyre Size:	206/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,584.40	2,711.52	2,872.88	51.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,110.00	950.00	46.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,644.40	3,821.52	3,822.88	50.01
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	7,644.40	3,050.00	4,594.40	60.10
+ GST 7.00/7.00% (S\$)	535.11	213.50	321.61	60.10
Nett Amount (S\$)	8,179.51	3,263.50	4,916.01	60.10

INSPECTION

Date of Assignment:	08/06/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	09/06/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2022)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH9418C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Serviceable	2,508.80 FL	*- FL
2	1		*FRT BUMPER	Deformed	1,052.20 FL	*1,052.20 FL
3	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*FRT BUMPER UPR BRKT LH	Necessary	22.40 FL	*22.40 FL
5	1		*FRT BUMPER SIDE RETAINER LH	Necessary	24.60 FL	*24.60 FL
6	1		*HEADLAMP LH	Cracked	1,388.00 FL	*1,388.00 FL
7	1		*FRT FENDER LH	Dented	663.00 FL	*663.00 FL
8	1		*FRT FENDER SHIELD LH	Not Necessary	174.90 FL	*- FL
9	1		*FRT WHEEL CAP LH	Scratched	217.20 FL	*217.20 FL
10	1		*HEADLAMP SUPPORT PANEL	Serviceable	907.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,980.50	3,389.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,396.10	677.88
Total Parts (\$\$)	5,584.40	2,711.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	560.00
2	SPRAY PAINTING	New	900.00	500.00
3	CHECK LIGHTINGS	New	40.00	20.00
4	TUFF KOTE	New	80.00	30.00
5	WHEEL ALIGNMENT	New	120.00	0.00
6	R/I RADIATOR ETC	New	120.00	0.00
Gross Labour Cost (\$\$)			2,060.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >