



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22005465/Any3m4

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 26/09/2022

ATTN: HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 9088H	Veh. Inspected	SFQ 6016E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1170829-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	08/06/2022

2. Vehicle Particulars & Condition

Make & Model	BMW 523i	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBAFP32070C544981	Colour	BLACK
Odometer	191889 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	PIRELLI	6 mm
L/H Front Tyre	245/45 R18	PIRELLI	6 mm
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/05/2022	Inspect Date / Time	08/06/2022 (11:24 AM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------