

Huey Yon (LKKAuto)

From: frontdesk@tlmotor.com.sg
Sent: Thursday, 15 June 2023 12:43 PM
To: Huey Yon (LKKAuto)
Cc: SUR
Subject: RE: SJL 81J-C10015688 /CD- DOA: 04/06/2022

Thank you, Huey Yon.

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Sent: Thursday, June 15, 2023 11:26 AM
To: frontdesk@tlmotor.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJL 81J-C10015688 /CD- DOA: 04/06/2022

Dear Patricia,

Please submit your LOD with lump sum \$1,800.00 and 2 repair days to AUTO & GENERAL insurance company.

Best Regards,
Huey Yon | Case Handler
LKK Auto Consultants
phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: frontdesk@tlmotor.com.sg <frontdesk@tlmotor.com.sg>
Sent: Wednesday, June 14, 2023 8:35 PM
To: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Subject: RE: SJL 81J-C10015688 /CD- DOA: 04/06/2022

This is your recommendation, why need to subject approval?

Regards,
[Patricia Tan](#)

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Sent: Wednesday, June 14, 2023 11:20 AM
To: frontdesk@tlmotor.com.sg
Subject: RE: SJL 81J-C10015688 /CD- DOA: 04/06/2022

Dear Patricia,

Re-send

Without prejudice

We will be advising our principal a cost of repair at Lump sum \$1,800.00 with 2 days of repair, subject to their approval.

Best Regards,
Huey Yon | Case Handler
LKK Auto Consultants

phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: frontdesk@tlmotor.com.sg <frontdesk@tlmotor.com.sg>
Sent: Wednesday, June 14, 2023 10:30 AM
To: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Subject: RE: SJL 81J-C10015688 /CD- DOA: 04/06/2022

Dear Huey Yon,

Our calculation is \$1800.00, if your end adjusted the sensor to \$300SN.

Await for your reply.

Rdgs,
Patricia Tan

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Sent: Wednesday, June 14, 2023 8:18 AM
To: frontdesk@tlmotor.com.sg
Subject: SJL 81J-C10015688 /CD- DOA: 04/06/2022

Dear Sir/Mdm,

Without prejudice

We will be advising our principal a cost of repair of Lump sum \$1,700.00 with 2 days of repair, subject to their approval.

Best Regards,
Huey Yon | Case Handler
LKK Auto Consultants
phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Virus-free. www.avast.com