



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Budget Direct Insured's Veh No : SMQ3310S  
Date of Accident : 04 June 2022

Miss Lim Seow Leng

Date : 13 June 2022

Estimate To Repair SJL81J - Lexus IS300 4DR SEDAN (AUTO) (2WD) E  
Chassis No : JTHBA1D2805112229

S/No	Quantity	Description	Amount
	nett	<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>3er Deam</i>	\$ 985.00
02	10 pcs	rear bumper clip @ \$4.50 <i>NEC</i>	\$ 45.00
03	1 pc	rear bumper lower <i>for cut</i>	\$ 664.30
04	2 pcs	rear bumper parking sensor @ \$490.80 <i>3 Family</i>	\$ 981.60
05	1 pc	rear bumper sponge <i>?X nn</i>	\$ 125.00
06	1 pc	rear bumper reinforcement <i>?X nn</i>	\$ 685.00
07	2 pcs	rear bumper reinforcement bracket @ \$85.00 <i>?X nn</i>	\$ 170.00
			\$ 3,665.90
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		Putty and spray painting of the affected portion.	\$ 500.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
03		To reinstall of rear bumper parking sensor.	\$ 80.00
04		To check electrical lighting concerned.	\$ 80.00
			\$ 1,160.00
		Total	\$ 4,825.90

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: