

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SJ LEASING PTE LTD
60 JALAN LAM HUAT #05-11 CARROS
CENTRE
SINGAPORE 737869

Contact : 85255530, 86612668

TP Budget Direct.
Hill King

TAX INVOICE

Repair Code : CLM17240

Date in : 07/06/2022

Vehicle Num. : SLP294S

Model : MAZDA3 SEDAN 1.5 AT EU6

Chassis/Eng# : JM6BN22A8H0151225/P520442506

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>new</i>	1	957.40	+ 957.40
REAR BOOTLID 'LOGO' EMBLEM <i>3 new</i>	1	74.40	+ 74.40
REAR BOOTLID 'MAZDA 3' EMBLEM	1	93.40	+ 93.40
REAR BOOTLID 'SKYACTIV TECHNOLOGY' EMBLEM <i>new</i>	1	63.60	+ 63.60
REAR BOOTLID RUBBER SEAL <i>new</i>	1	129.30	+ 129.30
REAR BUMPER <i>behind</i>	1	1168.60	1168.60 <i>1065</i>
REAR BUMPER CENTER BRACKET <i>centered</i>	1	15.10	✓ 15.10
REAR BUMPER REINFORCEMENT <i>centered</i>	1	628.70	628.70 <i>498</i>
REAR BUMPER SIDE BRACKET L/R <i>new</i>	2	21.00	✓ 42.00
REAR BUMPER SIDE BRACKET RIVET L/R <i>new</i>	4	5.90	✓ 23.60
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	36.10	✓ 72.20
REAR BUMPER TOW HOOK COVER <i>new Missing</i>	1	20.20	✓ 20.20
REAR END PANEL <i>new</i>	1	505.10	+ 505.10
Subtotal before discount			3,793.60
Percentage discount 20%			758.72
Sub-total 1			3,034.88
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	50.00	+ 50.00
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SJ LEASING PTE LTD
60 JALAN LAM HUAT #05-11 CARROS
CENTRE
SINGAPORE 737869

Contact : 85255530, 86612668

TAX INVOICE

Repair Code : CLM17240

Date in : 07/06/2022

Vehicle Num. : SLP294S

Model : MAZDA3 SEDAN 1.5 AT EU6

Chassis/Eng# : JM6BN22A8H0151225/P520442506

REAR BUMPER REVERSE SENSOR - SET	1	250.00	200	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	40.00	✓	40.00
REAR END PANEL SEALANT	1	80.00	✓	80.00
Subtotal before discount				470.00
Percentage discount 0%				0.00
Sub-total 2				470.00
Parts-total				3,504.88

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and reinstall exhaust pipe.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

2,560.00

6,064.88

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin Lj
1/1 15/06/22.
03 Days.

to total: 2250.80
L/S: 1.81c
1.81c