

REF: CS1/SCD22005482/Tqy3

Special Instruction:

ASSIGNMENT (Office)

From (Person): RALF TAY of SCD Date/Time: 07/06/2022
Estimated Cost: _____ Bill to: _____

LS : \$ 3800 / 5 DAYS

Third Parties:

Claimant:

Surveyor: SCL APPRAISER

Workshop: HOCK MOTORS
WORKSHOP

OD/TP Re-inspection	Evaluation
1. The OD/TP Re-inspection is performed by the same person who performed the initial inspection. 2. The OD/TP Re-inspection is performed within 30 days of the initial inspection. 3. The OD/TP Re-inspection is performed at the same location as the initial inspection. 4. The OD/TP Re-inspection is performed using the same equipment as the initial inspection. 5. The OD/TP Re-inspection is performed using the same methodology as the initial inspection. 6. The OD/TP Re-inspection is performed using the same criteria as the initial inspection. 7. The OD/TP Re-inspection is performed using the same personnel as the initial inspection. 8. The OD/TP Re-inspection is performed using the same documentation as the initial inspection. 9. The OD/TP Re-inspection is performed using the same communication as the initial inspection. 10. The OD/TP Re-inspection is performed using the same training as the initial inspection.	1. The OD/TP Re-inspection is performed by the same person who performed the initial inspection. 2. The OD/TP Re-inspection is performed within 30 days of the initial inspection. 3. The OD/TP Re-inspection is performed at the same location as the initial inspection. 4. The OD/TP Re-inspection is performed using the same equipment as the initial inspection. 5. The OD/TP Re-inspection is performed using the same methodology as the initial inspection. 6. The OD/TP Re-inspection is performed using the same criteria as the initial inspection. 7. The OD/TP Re-inspection is performed using the same personnel as the initial inspection. 8. The OD/TP Re-inspection is performed using the same documentation as the initial inspection. 9. The OD/TP Re-inspection is performed using the same communication as the initial inspection. 10. The OD/TP Re-inspection is performed using the same training as the initial inspection.

To Inspect Vehicle No: SMA 539D Insured: QX 2076R

at Workshop m/s HOCK MOTORS WORKSHOP Tel:

of NO.1 KAKI BUKIT AVE 6 #02-38 AUTOBAY @KAKI BUKIT SINGAPORE 417883

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 03/05/2022
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 05/07/22 Confirmed with _____ Final Fig _____, ____ days (Red \$ ____/____%; Original! ____ days)

Date/Time: 05/07/22 Submit ~~Final Fig~~ LS \$2300, 4 days (Red \$ 1500 / 39 %; Original 5 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____