

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22005483/UYA3Q2**Date:** 24/05/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SMA6283B **Insured Vehicle No :** SLU1225J
 Date of Loss: 02/06/2022 Nature of Claim: TP Claim No: MFL2022D0003019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA6283B**
 Make & Model: BMW 428i, 2.0 Coupe (A) Engine No: C4380723N20B20A
 Reg. Date: 03/03/2014 (Man. Year: 2014) Chassis No: WBA3N320X0K238226
 Colour: Blue Odometer: 158315 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35Z R19 Rear Tyre Size: 265/30Z R19
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,522.75	1,844.96	677.79	26.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	840.00	350.00	490.00	58.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,362.75	2,194.96	1,167.79	34.73
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	3,362.75	1,700.00	1,662.75	49.45
+ GST 7.00/7.00% (S\$)	235.39	119.00	116.39	49.45
Nett Amount (S\$)	3,598.14	1,819.00	1,779.14	49.45
+ Car Rental (3.0 x S\$130.00/day) (S\$)		390.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,216.45		

INSPECTION

Date of Assignment: 10/06/2022
 Date Inspected: 10/06/2022 Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD.
 Singapore 417883
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2023)
Parts:	M1-COUPE	BMW 428i 2.0 Coupe (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA6283B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Warped	1,889.43 FN	*1,889.43 FN
2	1		*FRONT BUMPER BMW LOGO	Not Necessary	89.95 FN	*- FN
3	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	180.35 FN	*- FN
4	2		*FRONT BUMPER SIDE RETAINERS -R/L	Not Necessary	179.90 FN	*- FN
5	1		*FRONT BUMPER SPONGE	Not Necessary	181.62 FN	*- FN
6	1		*FRONT BUMPER SPRAY NOZZLE COVER -LH	Not Necessary	81.65 FN	*- FN
7	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (\$\$)					2,652.90	1,939.43
- Nett Item Discount on N Items 5.00/5.00% (\$\$)					130.15	94.47
Total Parts (\$\$)					2,522.75	1,844.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	40.00	0.00
2	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS	New	400.00	200.00
3	TO PANEL BEAT ,CUT ,WELD REMOVE & REPLACE DAMAGED PARTS	New	400.00	150.00
Gross Labour Cost (S\$)			840.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >