

Plate Number	Case Number	Brand	Details	Body Type	Insurance company	Export CSV
SMA6283B	-	BMW	4-Series Gran Coupe	Coupe	-	

Technician	SA	Parts Manager
-	LKK_cs-a	-

Parts

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	Front bumper <div>Customized</div>			\$0.00	\$1889.43	-5 %	1	\$1794.96
								Total :\$1794.96

Materials

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	Front bumper clips - set <div>Customized</div>			\$0.00	\$50.00	0 %	1.0	\$50.00
								Total :\$50.00

Labors

Replace / RnR

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
01	Panel beating <div>Customized</div>		RnR	0.00	\$150.00	0 %	\$150.00
							Total :\$150.00

Paint

#	Description	Labor Code	degree	Labor Hour	Unit Price	Mark up/Disc	Sum
01	Spray painting <div>Customized</div>		Full spray	0.00	\$200.00	0 %	\$200.00
							Total :\$200.00

Remarks 1 remarks

2023-04-13 23:10 Assessor Supervisor-Insurlogic 4 42797773348
FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$1,700.00 WITH 2 WORKING DAYS